



report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC TDCI
Colour	Blue
Year of manufacture	-
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg






Internet history

Entry 1

Date	2021-06-17
Pictures	4
Listing price	View report



source: autotrader.co.uk



**MOT history**

MOT #14	2023-06-27 16:21
MOT test number	991504045894
Result	✓ Passed
Next expiry date	2024-06-26
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #13	2022-05-20 10:02
MOT test number	526083685672
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Reversing lights not working
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #12	2022-05-20 10:02
MOT test number	619841954436
Result	✗ Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Pass with rectification	Offside Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Reversing lights not working

MOT #11	2020-10-28 15:04
MOT test number	406633494917
Result	✓ Passed

**MOT #10** 2019-07-03 11:05**MOT test number** 349538515920**Result** ✓ Passed**MOT #9** 2018-07-05 13:45**MOT test number** 721088826547**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #8** 2018-07-04 09:38**MOT test number** 737351559513**Result** ✗ Failed**Advice** Play in steering rack inner joint(s)**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #7** 2017-06-22 11:29**MOT test number** 242067315459**Result** ✓ Passed**Advice** Reverse lights not working**Advice** Back exhaust box delaminating**MOT #6** 2017-06-22 07:51**MOT test number** 237625173008**Result** ✗ Failed**Advice** Reverse lights not working**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Back exhaust box delaminating**MOT #5** 2016-07-01 09:48**MOT test number** 521681076039**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 2.00 mm on outer edge 195/60/15 (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3.00mm (4.1.E.1)**MOT #4** 2015-07-03 10:51**MOT test number** 128714485156**Result** ✓ Passed**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Advice** Direction indicators slightly discoloured (1.4.A.2f)**Notice** Rear silencer corroded



MOT #3	2014-06-12 16:10
MOT test number	245643364496
Result	✓ Passed

MOT #2	2013-07-01 10:23
MOT test number	659982883105
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear wheel bearing has slight play (2.6.2)
Notice	Nail in nearside rear tyre

MOT #1	2012-06-18 10:53
MOT test number	529960172137
Result	✓ Passed
Notice	Nearside rear wheel bearing noisy



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-07-08
Last registration	2023-06-27
Complete history	See info



Registration #1	2009-07-08	15 mi
Registration #2	2012-06-18	44.880 mi
Registration #3	2013-07-01	55.225 mi
Registration #4	2014-06-12	58.540 mi
Registration #5	2015-07-03	71.861 mi
Registration #6	2016-07-01	81.412 mi
Registration #7	2017-06-22	91.019 mi
Registration #8	2017-06-22	91.019 mi
Registration #9	2018-06-22	91.019 mi
Registration #10	2019-06-22	91.019 mi
Registration #11	2020-06-22	91.019 mi
Registration #12	2021-06-22	91.019 mi
Registration #13	2022-06-22	91.019 mi
Registration #14	2023-06-27	91.019 mi
Registration #15	2023-06-27	91.019 mi
Registration #16	2023-06-27	91.019 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1162 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9R00248