





report date: 2024-03-28

General information

| Make | NISSAN |
|---------------------|----------------------------|
| Model | NAVARA DCI N-GUARD SHR DCB |
| Colour | Black |
| Year of manufacture | 2019 |
| Top speed | 112 mph |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| Power | 190 BHP |
|-------------------------|---------------------|
| Max. torque | 450 Nm at 2.000 rpm |
| Engine capacity | 2.298 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 40.9 mpg |
| CO2 emission | 183 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 1

Date 2022-07-29

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



| MOT hist | orv |
|----------|-----|
|----------|-----|

| MOT expiry date | 2024-08-09 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 1 |
| Total items failed | 0 |

| MOT #3 | 2023-08-04 10:04 |
|------------------|------------------|
| MOT test number | 576407177268 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-09 |

| MOT #2 | 2022-08-10 13:54 |
|-----------------|------------------|
| MOT test number | 293030400034 |
| Result | ✓ Passed |

| MOT #1 | 2022-02-26 08:18 |
|---|------------------|
| MOT test number | 172280502517 |
| Result | ✓ Passed |
| Advice Nearside Rear Light unit damaged | |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status | Valid until 1 September |
|------------------|-------------------------|
| Days left | 124 |
| MOT expiry date | 9 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | |
|---|-------------|
| | |
| *************************************** | |
| | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Current registration | NK SIN |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 7/10



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2019-03-01 |
| Last registration | 2023-08-04 |
| Complete history | See info |



| Registration #1 | 2019-03-01 | 17 mi |
|-----------------|------------|-----------|
| Registration #2 | 2022-02-26 | 23.287 mi |
| Registration #3 | | 11.177 es |
| Registration #4 | | 77,777 66 |
| Registration #5 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



WJ19MDK

report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 78% |
| Pedestrian | 78% |
| Safety systems | 68% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| Width | 1850 mm |
|---------------------|---------|
| Height | 1840 mm |
| Length | 5330 mm |
| Wheel base | 3150 mm |
| Kerb weight | 1987 kg |
| Max. allowed weight | 3045 kg |

Additional information

| Fuel tank capacity | 73 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 10 |

Number of axles 2
Engine number 070186C