



V009XVE

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 350 H/R P/V
Colour	Orange
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2023-11-13
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	18
Total items failed	29

MOT #17	2022-11-14 13:34
MOT test number	605976274547
Result	✓ Passed
Next expiry date	2023-11-13

MOT #16	2021-09-23 10:43
MOT test number	491678147036
Result	✓ Passed

MOT #15	2020-08-20 11:56
MOT test number	191490907143
Result	✓ Passed

MOT #14	2019-08-22 09:12
MOT test number	818541512999
Result	✓ Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13**

2019-08-20 10:09

MOT test number

909835076427

Result**✗ Failed**

- Fail** Offside Front Driver's door does not latch securely closed (6.2.3 (a))
- Fail** Offside Outer Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill marked in yellow (6.2.2 (d) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill marked in yellow (6.2.2 (d) (i))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #12

2018-08-16 09:46

MOT test number

798895914080

Result**✓ Passed**

- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

2017-08-08 11:17

MOT test number

966477189654

Result**✓ Passed**

**MOT #10** 2016-07-15 10:42**MOT test number** 559709409668**Result** ✓ Passed**MOT #9** 2016-07-14 13:26**MOT test number** 559623863632**Result** ✗ Failed

- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front Obligatory mirror seriously obscured affecting the rear view (8.1.2a)
- Fail** Nearside Front Anti-roll bar has excessive play in a pin/bush broken (2.4.G.2)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #8 2015-07-17 11:26**MOT test number** 975048595190**Result** ✓ Passed**MOT #7** 2014-07-19 09:35**MOT test number** 186260204214**Result** ✓ Passed

- Advice** Driver's door pillar deteriorated but the door can still be readily opened and closed (6.2.B.2)

**MOT #6**

2014-07-17 10:24

MOT test number

688648694151

Result**✗ Failed**

- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Advice** Driver's door pillar deteriorated but the door can still be readily opened and closed (6.2.B.2)

MOT #5

2014-01-29 15:17

MOT test number

197369624027

Result**✗ Failed**

- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Brake fluid warning lamp illuminated (3.6.G.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside rear brake binding (3.7.B.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #4 2013-03-20 16:12

MOT test number 229029173089

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Rear brake discs worn

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Front brake discs worn

MOT #3 2013-03-20 16:12

MOT test number 516329573041

Result ✗ Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (1.7.5a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Rear brake discs worn

Pass with rectification Offside Rear Direction indicators incorrect colour (1.4.A.2f)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Front brake discs worn

MOT #2 2012-04-19 15:25

MOT test number 918000612179

Result ✓ Passed

MOT #1 2012-04-19 15:25

MOT test number 269060512407

Result ✗ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	VO09XVE
Plate since	2019-09-28
Current registration	VO09XVE
Plate since	2019-09-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-04-22
Last registration	2022-11-14
Complete history	See info



Registration #1	2009-04-22	7 mi
Registration #2	2012-04-19	90.898 mi
Registration #3	2013-03-20	122.407 mi
Registration #4	2014-01-29	152.682 mi
Registration #5	2014-07-17	152.764 mi
Registration #6	2014-07-19	152.764 mi
Registration #7	2015-07-17	158.823 mi
Registration #8	2016-07-14	167.091 mi
Registration #9	2016-07-14	167.091 mi
Registration #10	2016-07-14	167.091 mi
Registration #11	2016-07-14	167.091 mi
Registration #12	2016-07-14	167.091 mi
Registration #13	2016-07-14	167.091 mi
Registration #14	2016-07-14	167.091 mi
Registration #15	2016-07-14	167.091 mi
Registration #16	2016-07-14	167.091 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2374 mm
Height	2543 mm
Length	5680 mm
Kerb weight	2062 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	8K44781