





General information

| Make | MAZDA |
|---------------------|-----------------|
| Model | RX-8 RX-8 231PS |
| Colour | Red |
| Year of manufacture | 2004 |
| Top speed | 146 mph |
| 0 - 60 mph | 6.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 238 BHP |
|-------------------------|---------------------|
| Max. torque | 211 Nm at 5.500 rpm |
| Engine capacity | 2.616 cc |
| Cylinders | 2 |
| Fuel type | Petrol |
| Consumption city | 17.9 mpg |
| Consumption extra urban | 31.7 mpg |
| Consumption combined | 24.8 mpg |
| CO2 emission | 284 g/km |
| CO2 label | Μ |





MOT history

| MOT expiry date | 2015-04-09 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 8 |
| Failed MOT tests | 3 |
| Total advice items | 12 |
| Total items failed | 4 |

| MOT #11 | 2014-04-10 11:49 |
|------------------|------------------|
| MOT test number | 819020304119 |
| Result | ✓ Passed |
| Next expiry date | 2015-04-09 |

| MOT #10 | 2013-03-18 13:20 |
|----------|--|
| MOT test | number 919987973051 |
| Result | ✓ Passed |
| Advice | Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |
| Advice | Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |

| MOT #9 | 2012-04-10 15:58 |
|--|------------------|
| MOT test number | 536321802187 |
| Result | ✓ Passed |
| Notice Exhaust back box xlamp corroded | |

| MOT #8 | | 2012-04-10 15:58 |
|-------------------------|------------------------------------|------------------|
| MOT test number | | 575491202168 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Headlamp aim too low (1.8) | |
| Notice Exhaust back bo | x xlamp corroded | |





| MOT #7 | 2011-06-06 08:47 |
|-----------------|------------------|
| MOT test number | 219067451160 |
| Result | ✓ Passed |
| | |
| МОТ #6 | 2010-10-16 10:53 |
| MOT test number | 680199180220 |
| Result | ✓ Passed |

Notice Front windows tinted.

| MOT #5 | | 2009-05-06 10:10 |
|----------|---|------------------|
| MOT test | number | 423496929187 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Both front tyres rubber cracking | |

| МОТ #4 | 2009-05-02 12:32 |
|--|------------------|
| MOT test number | 261472629111 |
| Result | × Failed |
| Fail Offside Rear Anti-roll bar linkage insecure (2.4.G.1) | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Notice Both front tyres rubber cracking | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #3 | 2008-04-23 16:59 |
|-----------------|------------------|
| MOT test number | 284784118434 |
| Result | ✓ Passed |





| MOT #2 | 2008-04-23 11:47 |
|--|------------------|
| MOT test number | 962004218167 |
| Result | 🗙 Failed |
| Fail Offside Front Anti-roll bar linkage insecure (2.4.G.1) | |
| Notice Both front tyres starting to crack | |
| Fail Nearside Front Anti-roll bar linkage insecure (2.4.G.1) | |
| | |
| MOT #1 | 2007-04-25 15:21 |

| MOT test number | 473845417184 |
|-----------------|--------------|
| Result | ✓ Passed |



Tax & MOT check

| X Untaxed | Х MOT |
|-----------------------------|--------------------------|
| Tax expired: 1 June 2014 | Expired: 9 April 2015 |
| Tax status | Expired at 1 June 2014 |
| Days left | 3619 days too late |
| MOT expiry date | 9 April 2015 |
| Full MOT history | See MOT history |
| | |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | К |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | 4. ARANPE |
| Туре | |
| Damage 2 | AMPL |
| Damage 2 | E CUT-S |
| Date | * |
| Category | AMP |
| Туре | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ana | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2004-01-15 |
| Last registration | 2014-04-10 |
| Complete history | See info |



| Registration #1 | 2004-01-15 | 27 mi |
|------------------------------------|------------|--|
| Registration #2 | 2007-04-25 | 27.034 mi |
| Registration #3 | 2008-04-23 | 33.921 mi |
| Registration #4 | 2008-04-23 | 33.921 mi |
| Registration #5 | 2009-05-02 | 41.859 mi |
| Registration #6 | 2009-05-06 | 41.859 mi |
| | | |
| Registration #7 | | 11.777 mi |
| Registration #7 Registration #8 | | 10.000 est |
| - | | 01,000 est 01,000 est 01,000 est |
| Registration #8 | | 01,000 est 01,000 est 01,000 est 01,000 est |



Dimensions & weight

| Width | 1771 mm |
|---------------------|---------|
| Height | 1340 mm |
| Length | 4435 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1350 kg |
| Max. allowed weight | 1815 kg |

Additional information

| Fuel tank capacity | 61 |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 4 |
| Number of seats | 4 |
| Engine number | 13B 445541 |