




General information

Make	SUZUKI
Model	SPLASH GLS
Colour	Turquoise
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





## Internet history

### Entry 1

Date	2021-01-21
Pictures	13
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)



MOT history

<b>MOT expiry date</b>	2024-04-18
<b>MOT pass rate</b>	71 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	3
<b>Total items failed</b>	6

<b>MOT #17</b>	2023-04-19 13:51
<b>MOT test number</b>	943815196462
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-04-18
<b>Minor</b>	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

<b>MOT #16</b>	2022-03-03 15:12
<b>MOT test number</b>	459872335589
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2022-03-03 11:35
<b>MOT test number</b>	429638413071
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
<b>Fail</b>	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
<b>Fail</b>	Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

<b>MOT #14</b>	2021-03-09 09:47
<b>MOT test number</b>	436582430759
<b>Result</b>	✓ Passed



MOT #13	2019-09-16 14:28
MOT test number	898469164656
Result	✓ Passed

MOT #12	2018-09-14 07:18
MOT test number	900011064278
Result	✓ Passed

MOT #11	2018-09-13 14:03
MOT test number	766495774551
Result	✗ Failed
<b>Fail</b>	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10	2017-09-01 10:50
MOT test number	305010598427
Result	✓ Passed

MOT #9	2016-09-12 09:48
MOT test number	966031274822
Result	✓ Passed

MOT #8	2016-09-12 09:48
MOT test number	532208434100
Result	✗ Failed
<b>Pass with rectification</b>	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #7	2015-09-09 10:01
MOT test number	274402461521
Result	✓ Passed



MOT #6 2014-09-04 10:59

MOT test number 207707044210

Result ✓ Passed

MOT #5 2014-09-04 10:59

MOT test number 679847544286

Result ✗ Failed

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #4 2013-09-06 16:03

MOT test number 666669843271

Result ✓ Passed

MOT #3 2013-09-05 09:28

MOT test number 955708843292

Result ✗ Failed

**Fail** Offside Front coil spring broken (2.4.C.1a)

MOT #2 2012-08-30 11:43

MOT test number 387153542242

Result ✓ Passed

**Notice** N/S/R TYRE PERISHED & CRACKED IN TREAD - ADVISE REPLACEMENT

MOT #1 2011-08-23 08:44

MOT test number 488525531292

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✗  
**MOT**

**Expired:**  
18 April 2024

**Tax status** Valid until 1 June

**Days left** 34

**MOT expiry date** 18 April 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



**Damage history**

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra SUZUKI salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	GJ58RTV
Plate since	2019-09-29
Current registration	GJ58RTV
Plate since	2019-09-29

More info >



**Finance check**

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled. If not, and you buy this SUZUKI then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this SUZUKI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	18
<b>First mileage registration</b>	2008-09-19
<b>Last registration</b>	2023-04-19
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2008-09-19	25 mi
<b>Registration #2</b>	2011-08-23	11.522 mi
<b>Registration #3</b>	2012-08-30	15.279 mi
<b>Registration #4</b>	2013-09-05	19.071 mi
<b>Registration #5</b>	2013-09-06	19.071 mi
<b>Registration #6</b>	2014-09-04	24.843 mi
<b>Registration #7</b>	2015-09-09	33.830 mi
<b>Registration #8</b>	2016-09-12	40.689 mi
<b>Registration #9</b>	2016-09-12	40.689 mi
<b>Registration #10</b>	2017-09-12	40.689 mi
<b>Registration #11</b>	2017-09-12	40.689 mi
<b>Registration #12</b>	2017-09-12	40.689 mi
<b>Registration #13</b>	2017-09-12	40.689 mi
<b>Registration #14</b>	2017-09-12	40.689 mi
<b>Registration #15</b>	2017-09-12	40.689 mi
<b>Registration #16</b>	2017-09-12	40.689 mi
<b>Registration #17</b>	2017-09-12	40.689 mi
<b>Registration #18</b>	2017-09-12	40.689 mi

[More info >](#)



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3715 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1111159