





report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Silver
Year of manufacture	2009
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date	2022-06-09
Pictures	1
Listing price	View report



source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-10
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	17
Total items failed	6

MOT #15	2023-07-11 14:54
MOT test number	885144656924
Result	✓ Passed
Next expiry date	2024-07-10

MOT #14	2022-06-16 11:00
MOT test number	967660231255
Result	✓ Passed

MOT #3	13	2022-06-08 16:09
MOT te	st number	885217560336
Result		🗙 Failed
Fail	Offside Front Lower Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))	
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #12		2021-05-18 15:38
MOT test	number	805281015442
Result		✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10

MOT test number

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT test number

Result

Advice
Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice
Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #8
 2017-05-16 12:06

 MOT test number
 657071957610

 Result
 ✓ Passed

 MOT #7
 2017-05-15 11:16

 MOT test number
 990396709200

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #6 2016-05-19 11:23

MOT test number 989551789883

Result ✓ Passed

MOT #5 2015-05-18 12:59

MOT test number 107008735160

Notice Under-trays fitted obscuring some underside components

Notice Child seat fitted not allowing full inspection of adult belt

Notice Engine covers fitted obscuring some components in the engine bay

MOT #4 2014-05-30 16:23

MOT test number 289710954124

Result ✓ Passed

MOT #3 2014-05-30 10:25

MOT test number 986440754140

Result X Failed

Fail Nearside Inner Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Inner Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2 2013-06-03 11:28

MOT test number 208444453439

Advice Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number 638680362145

Result ✓ Passed

Notice NSR tyre tread worn on inner edge

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Notice Nail in offside rear tyre

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincore

HV59RMY

report date: 2024-03-28

More info >

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HONDA had different number plates.

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-29
Last registration	2023-07-11
Complete history	See info



Registration #1	2009-09-29	11 mi
Registration #2	2012-06-08	24.671 mi
Registration #3	2013-06-03	29.346 mi
Registration #4	2014-05-30	33.929 mi
Registration #5	2014-05-30	33.929 mi
Registration #6	2015-05-18	37.204 mi
Registration #7	2016-05-19	40.517 mi
Registration #8	2017-05-15	43.505 mi
Registration #9	2017-05-16	43.505 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4740 mm
Wheel base	2705 mm
Kerb weight	1559 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N22B11105454

CarCheck.co.uk page 13/13