






report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SE LUX
Colour	Black
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	37.2 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-06

Pictures 4

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-04-26
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #11		2023-04-18 11:42
MOT test	number	570848282297
Result		✓ Passed
Next expi	ry date	2024-04-26
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice bone bush	Offside Front Suspension arm pin or bush worn but not resulting in excessive (5.3.4 (a) (i))	movement Wish

MOT #10	2022-04-27 15:21
MOT test number	828946355925
Result	✓ Passed
MOT #9	2022-04-27 12:59
MOT test number	729571364118
Result	★ Failed
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #8	2020-11-06 09:43
MOT test number	557164669562
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6

MOT test number

Result

MOT #5

MOT test number

2017-11-23 09:58

MOT test number

624147579298

Result

Advice

Nearside Front nearside front tyre has cuts in wall

MOT test number

France

MOT test number

573165346468

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Engine covers fitted

Advice

Offside Rear Tyre worn close to the legal limit 2.2mm (4.1.E.1)

MOT #3

MOT test number

875627191349

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #2
 2014-12-01 15:41

 MOT test number
 667425534347

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2014-11-28 14:56

MOT test number 925742234334

Result

X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice

Nail in nearside rear tyre

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	3
MOT expiry date	26 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

ND61LWA

report date: 2024-03-28

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-01-10
Last registration	2023-04-18
Complete history	See info



Registration #1	2012-01-10	18 mi
Registration #2	2014-11-28	22.082 mi
Registration #3	2014-12-01	22.134 mi
Registration #4	2015-11-02	30.087 mi
Registration #5	2016-11-23	40.997 mi
Registration #6	2017-11-23	47.768 mi
Registration #7	2018-11-28	54.697 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 44
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		10.377 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12

Engine number

1068698