



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-09
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #20	2021-10-26 10:14
MOT test number	296629065179
Result	✓ Passed
Next expiry date	2022-10-25
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19	2020-10-20 11:08
MOT test number	564983827631
Result	✓ Passed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18	2020-10-20 11:08
MOT test number	532096040034
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2019-10-23 13:20
MOT test number	376395554203
Result	✓ Passed

**MOT #16**

2019-10-15 11:58

MOT test number

619554959876

Result**✗ Failed**

- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- MAJOR** Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

MOT #15

2019-10-03 11:41

MOT test number

279754886125

Result**✗ Failed**

- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Under body rusty
- MAJOR** Rear Exhaust system insecure (6.1.2 (a))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #14**

2018-04-05 10:57

MOT test number

907361983716

Result

✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Front exhaust bracket broken
- Advice** Offside front tyre worn on outer edge
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Offside front outer sill soft
- Advice** Nearside front tyre worn on edges

MOT #13

2018-04-05 08:43

MOT test number

389065490200

Result

✗ Failed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside front outer sill soft
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Nearside front tyre worn on edges
- Advice** Front exhaust bracket broken
- Fail** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Offside front tyre worn on outer edge
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside front tyre soft

**MOT #12**

2017-03-08 13:37

MOT test number

624375857865

Result

✓ Passed

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #11**

2017-03-08 10:38

MOT test number

347083898772

Result

✗ Failed

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2016-03-09 11:12

MOT test number

506850823690

Result

✓ Passed

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Child seats fitted

Advice Front exhaust bracket broken

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Slight play on offside front inner steering rack end

Advice Rear exhaust strap corroded and broken

MOT #9

2015-04-08 14:29

MOT test number

717418895048

Result

✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

Notice Rear exhaust strap broken

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Front brake discs slightly worn

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #8**

2015-04-07 09:11

MOT test number

146777695006

Result**✗ Failed****Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front brake discs slightly worn**Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Rear exhaust strap broken**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #7**

2014-03-06 12:17

MOT test number

447495464010

Result**✓ Passed****Notice** Coolant level low**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Offside rear tyre badly cracked**MOT #6**

2014-03-06 11:15

MOT test number

988425164061

Result**✗ Failed****Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Headlamp aim not tested (1.8.A.1c)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Offside rear tyre badly cracked**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Coolant level low

**MOT #5** 2013-03-28 10:55**MOT test number** 346597583071**Result** ✓ Passed**Notice** Offside rear tyre outside wall has cracking**Notice** Nearside rear tyre outside wall has cracking**Notice** Offside rear light lense cracked**MOT #4** 2013-03-28 10:55**MOT test number** 176007783078**Result** ✗ Failed**Notice** Offside rear light lense cracked**Notice** Offside rear tyre outside wall has cracking**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Notice** Nearside rear tyre outside wall has cracking**MOT #3** 2012-03-29 11:20**MOT test number** 699959482038**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Nearside rear tyre sidewall cracked**Notice** Offside rear tyre sidewall cracked**MOT #2** 2011-03-18 11:18**MOT test number** 908707371097**Result** ✓ Passed



MOT #1	2010-03-23 11:11
MOT test number	484222880024
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-08-31
Last registration	2021-10-26
Complete history	See info



Registration #1	2007-08-31	8 mi
Registration #2	2010-03-23	17.620 mi
Registration #3	2011-03-18	25.300 mi
Registration #4	2012-03-29	31.196 mi
Registration #5	2013-03-28	39.005 mi
Registration #6	2014-03-06	47.060 mi
Registration #7	2014-03-06	47.060 mi
Registration #8	2015-04-07	56.813 mi
Registration #9	2015-04-08	56.813 mi
Registration #10	2016-03-09	63.538 mi
Registration #11	2017-03-08	71.654 mi
Registration #12	2018-03-08	79.770 mi
Registration #13	2019-03-08	87.886 mi
Registration #14	2020-03-08	95.999 mi
Registration #15	2021-03-08	104.112 mi
Registration #16	2022-03-08	112.225 mi
Registration #17	2023-03-08	120.338 mi
Registration #18	2024-03-08	128.451 mi
Registration #19	2025-03-08	136.564 mi
Registration #20	2026-03-08	144.677 mi
Registration #21	2027-03-08	152.790 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543