




report date: 2024-03-28

General information

Make	CITROEN
Model	C-CROSSER HDI EXCLUSIVE
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	379 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-02-10
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2025-03-14
<b>MOT pass rate</b>	81 %
<b>MOT passed</b>	13
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	19
<b>Total items failed</b>	7

**MOT #16** 2024-03-15 14:43**MOT test number** 688613626181**Result** Passed**Next expiry date** 2025-03-14

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Engine oil leak

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.6 mm (5.2.3 (e))

**MOT #15** 2023-01-27 15:15**MOT test number** 528986505789**Result** Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2022-02-15 16:21

**MOT test number**

248860441427

**Result**

✓ Passed

- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and offside (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material and offside (1.1.11 (c))

**MOT #13**

2022-02-08 17:52

**MOT test number**

235170967367

**Result**

✗ Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material and offside (1.1.11 (c))
- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Offside Front Suspension rod ball joint excessively worn (5.3.4 (a) (i))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and offside (5.2.3 (e))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #12**

2022-01-24 10:57

**MOT test number**

779005557775

**Result**

✗ Failed

- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** Nearside Rear brake disc corroded
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))

**MOT #11** 2021-01-11 17:14**MOT test number** 561688390275**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #10** 2020-01-13 16:07**MOT test number** 881357237244**Result** ✓ Passed**MOT #9** 2020-01-13 10:26**MOT test number** 523910406118**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #8** 2019-01-25 17:00**MOT test number** 867146355043**Result** ✓ Passed**MOT #7** 2018-01-12 12:08**MOT test number** 966668995884**Result** ✓ Passed**MOT #6** 2017-01-11 15:45**MOT test number** 365115793015**Result** ✓ Passed**MOT #5** 2016-01-11 12:14**MOT test number** 460428089940**Result** ✓ Passed



MOT #4	2015-09-03 16:09
MOT test number	655116323824
Result	✓ Passed
MOT #3	2014-05-27 16:30
MOT test number	958547144139
Result	✓ Passed
MOT #2	2013-05-17 14:39
MOT test number	588357233145
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
MOT #1	2012-05-21 09:55
MOT test number	305612142130
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
14 March 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	14 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-09-29
Current registration	 XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-04-21
Last registration	2024-03-15
Complete history	<a href="#">See info</a>



Registration #1	2009-04-21	29 mi
Registration #2	2012-05-21	22.821 mi
Registration #3	2013-05-17	35.653 mi
Registration #4	2014-05-27	47.624 mi
Registration #5	2015-09-03	63.955 mi
Registration #6	2016-01-11	66.774 mi
Registration #7	2017-01-11	73.063 mi
Registration #8	2018-01-12	79.690 mi
Registration #9	2019-01-25	87.459 mi
Registration #10	2020-01-25	95.228 mi
Registration #11	2021-01-25	102.997 mi
Registration #12	2022-01-25	110.766 mi
Registration #13	2023-01-25	118.535 mi
Registration #14	2024-01-25	126.304 mi
Registration #15	2025-01-25	134.073 mi
Registration #16	2026-01-25	141.842 mi
Registration #17	2027-01-25	149.611 mi
Registration #18	2028-01-25	157.380 mi

More info >



Dimensions & weight

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ694008020