





report date: 2024-03-28

General information

Make	FIAT
Model	PANDA EASY
Colour	Black
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2021-11-04

Pictures 20

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date 2021-10-02

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-10-02

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-08-25
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	10
Total items failed	4

MOT #8		2023-08-26 09:11
MOT test	number	640438305449
Result		✓ Passed
Next expiry date 2024-08-2		2024-08-25
Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))		
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

MOT #7		2023-08-26 09:11
MOT test number		705146223718
Result		X Failed
Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))		
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Rear Bra	ke hose has slight corrosion to ferrule (1.1.12 (f) (i))	

MOT #6	2022-08-25 15:36
MOT test number	733558358719
Result	✓ Passed

CarCheck.co.uk page 3/11



Result

SY17LHG report date: 2024-03-28

× Failed

MOT #5 2022-08-25 11:33

MOT test number 721862623298

Result X Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #4 2022-07-25 10:22

MOT test number 959557491509

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #3 2021-08-04 10:10

MOT test number 556881336942

Result ✓ Passed

Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))

MOT #2 2020-08-11 10:38

MOT test number 192362699232

Result \(\sqrt{Passed} \)

MOT #1 2020-06-09 05:14

MOT test number 494625962627

Result \(\sqrt{Passed} \)

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FIAT salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have?		
Check it in the premium report and see all owner registrations. Download the full report is	<u>nere</u> .	

	More info >	
	More into >	
Plate changes		
See in this check if this FIAT had different number plates.		
See in this check is that had amerene names places.		
Number of states		
Current registration	NE NE	
Plate since		
Current registration	OK SIE	
Fiele since	Un Company	
	More info >	

CarCheck.co.uk page 8/11



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-06-17
Last registration	2023-08-26
Complete history	See info



Registration #1	2017-06-17	26 mi
Registration #2	2020-08-11	23.481 mi
Registration #3	2021-08-04	32.448 mi
Registration #4		0.00 44
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		0.074
Registration #9		0.074
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 11/1:

Number of axles2Engine number2010393