





report date: 2024-03-29

General information

Make	MINI
Model	COUNTRYMAN COOPER S E ALL4
Colour	Silver
Year of manufacture	2018
Top speed	123 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Hybrid / Electric
Consumption combined	134.5 mpg
CO2 emission	49 g/km
CO2 label	A



CarCheck.co.uk page 1/11



FD67VSJ

report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-20

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-19

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-24
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #5	2024-01-23 16:28
MOT test number	592097058584
Result	✓ Passed
Next expiry date	2025-01-24

MOT #4	2024-01-22 11:08
MOT test number	223830868347
Result	X Failed
Fail Offside Front Tyre has a cut in excess of the requirements des	en enough to reach the ply or cords

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Registration plate insecure but not likely to fall off (0.1 (a))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #3		2023-01-24 10:43
MOT test	number	896037818077
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Also cracked/perished	ed (5.2.3 (e))

CarCheck.co.uk page 3/11



MOT #2 2022-01-25 10:00

MOT test number 954982792333

Result ✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2021-01-05 12:10

MOT test number 679299516152

Result \(\sqrt{Passed} \)

Advice Nearside Front tyre perishing

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



FD67VSJ

report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report h	
manners and the same of the sa	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-01-24
Last registration	2024-01-23
Complete history	See info



Registration #1	2018-01-24	25 mi
Registration #2	2021-01-05	12.488 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	80%
Pedestrian	64%
Safety systems	51%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1559 mm
Length	4299 mm
Wheel base	2670 mm
Kerb weight	1735 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	36 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/:

Engine number

G190H720