



report date: 2024-03-29

General information

Make	FORD
Model	KA KA LUXURY
Colour	Red
Year of manufacture	2005
Top speed	96 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	103 Nm at 2.500 rpm
Engine capacity	1.299 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2024-04-14
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	34
Total items failed	20

MOT #22	2023-04-15 10:41
MOT test number	668156969204
Result	✓ Passed
Next expiry date	2024-04-14
Minor	Offside Front Brake hose slightly chafed (1.1.12 (b) (i))
Advice	Nearside Rear Nail in tyre
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2023-04-11 15:10

MOT test number

203736207815

Result

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Minor** Offside Front Brake hose slightly twisted (1.1.12 (b) (i))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Nail in tyre
- Fail** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill area (7.1.1 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength axle mount area (5.3.6 (a) (i))

MOT #20

2022-03-30 13:52

MOT test number

832995336963

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Minor** Offside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2022-03-24 16:02

MOT test number

693674035777

Result**✗ Failed****Fail**

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail

Nearside Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Fail

Front Windscreen washer not working (3.5 (a))

Advice

Brake fluid close to minimum mark (1.1.10 (d) (ii))

Minor

Brake fluid warning lamp illuminated (1.1.10 (f))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Minor

Offside Front Brake hose slightly chafed (1.1.12 (b) (i))

Fail

Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #18

2021-03-25 12:15

MOT test number

165956400103

Result**✓ Passed****MOT #17**

2020-03-03 15:23

MOT test number

135714717848

Result**✓ Passed**

**MOT #16**

2019-03-06 14:58

MOT test number

736107341941

Result

✓ Passed

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #15**

2019-03-05 09:56

MOT test number

170687653791

Result

✗ Failed

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill area (5.3.6 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Items removed from driver's view prior to test**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive floor (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #14**

2018-03-20 11:42

MOT test number

182418709114

Result

✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #13** 2017-03-21 08:30**MOT test number** 280202654562**Result** ✓ Passed**MOT #12** 2016-03-14 14:20**MOT test number** 504636812593**Result** ✓ Passed**MOT #11** 2015-03-17 14:50**MOT test number** 275076875096**Result** ✓ Passed**MOT #10** 2015-03-17 08:27**MOT test number** 629816775023**Result** ✗ Failed**Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)**Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)**MOT #9** 2014-03-11 07:47**MOT test number** 959390474008**Result** ✓ Passed**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** Spare wheel incorrect size**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** Coolant leak**MOT #8** 2013-03-08 10:27**MOT test number** 556347563073**Result** ✓ Passed

**MOT #7** 2013-03-08 10:27**MOT test number** 537907363061**Result** ✗ Failed**Pass with rectification** Nearside Headlamp adversely affected by the operation of another lamp (1.7.5c)**MOT #6** 2012-03-13 11:17**MOT test number** 107363372071**Result** ✓ Passed**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #5** 2011-03-14 11:41**MOT test number** 678913571049**Result** ✓ Passed**MOT #4** 2011-03-14 11:41**MOT test number** 626073871035**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #3** 2010-03-17 10:22**MOT test number** 222736870029**Result** ✓ Passed**MOT #2** 2009-03-07 11:43**MOT test number** 312916169060**Result** ✓ Passed



MOT #1	2008-04-05 11:15
MOT test number	831456298004
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 June 2023

X

MOT

Expired:
14 April 2024

Tax status	Expired at 1 June 2023
Days left	333 days too late
MOT expiry date	14 April 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-10
Last registration	2023-04-15
Complete history	See info



Registration #1	2005-03-10	25 mi
Registration #2	2008-04-05	16.005 mi
Registration #3	2009-03-07	18.903 mi
Registration #4	2010-03-17	21.172 mi
Registration #5	2011-03-14	23.731 mi
Registration #6	2012-03-13	25.941 mi
Registration #7	2013-03-08	27.563 mi
Registration #8	2014-03-11	29.403 mi
Registration #9	2015-03-17	30.560 mi
Registration #10	2015-03-17	30.560 mi
Registration #11	2016-03-14	31.411 mi
Registration #12	2016-03-14	31.411 mi
Registration #13	2016-03-14	31.411 mi
Registration #14	2016-03-14	31.411 mi
Registration #15	2016-03-14	31.411 mi
Registration #16	2016-03-14	31.411 mi
Registration #17	2016-03-14	31.411 mi
Registration #18	2016-03-14	31.411 mi
Registration #19	2016-03-14	31.411 mi
Registration #20	2016-03-14	31.411 mi
Registration #21	2016-03-14	31.411 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Kerb weight	890 kg
Max. allowed weight	1265 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number

5P70071