



report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 1500TD LWB H/R P/V HDI
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	240 Nm at 1.900 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-09
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-13
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	51
Total items failed	0

MOT #20	2023-09-14 15:43
MOT test number	162995546368
Result	✓ Passed
Next expiry date	2024-09-13
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19	2023-09-05 08:49
MOT test number	655414689064
Result	✗ Failed
MAJOR	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
MAJOR	Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength wheel arch.. next to spring (5.3.6 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #18	2022-09-02 11:09
MOT test number	905796599092
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2022-09-01 09:23

MOT test number

878674029111

Result**✗ Failed**

MAJOR Nearside Front Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill corroded (6.1.1 (c) (i))

MAJOR Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced middle inner sill corroded (6.1.1 (c) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill corroded (6.1.1 (c) (i))

MOT #16

2021-09-07 11:49

MOT test number

283558213414

Result**✓ Passed**

Advice Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner sill to body (6.2.2 (d) (i))

Advice Rear both rear tyres perished on sidewalls

Advice Nearside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner sill (6.2.2 (d) (i))

MOT #15

2020-10-27 17:04

MOT test number

140453739132

Result**✓ Passed**

Advice Rear Tyre slightly damaged/cracking or perishing Both rear tyres inner / outer sidewalls perished but no cords showing. (5.2.3 (d) (ii))

MOT #14

2020-10-27 13:16

MOT test number

821289820954

Result**✗ Failed**

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively Badly split. (3.4 (b) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing Both rear tyres inner / outer sidewalls perished but no cords showing. (5.2.3 (d) (ii))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively Badly split. (3.4 (b) (ii))

**MOT #13**

2019-09-27 09:37

MOT test number

534515627754

Result

✓ Passed

Minor

Nearside Windscreen wiper blade defective split end (3.4 (b) (i))

Advice

Rear Tyre slightly damaged/cracking or perishing Both rear tyres have significantly perished outer side walls but no cords are visible. (5.2.3 (d) (ii))

MOT #12

2018-09-26 14:33

MOT test number

570479931878

Result

✓ Passed

Advice

Offside Rear Outer Tyre slightly damaged/cracking or perishing Outer sidewall perishing. (5.2.3 (d) (ii))

Advice

Nearside Rear Outer Tyre slightly damaged/cracking or perishing Outer sidewall perishing . (5.2.3 (d) (ii))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #11

2018-09-20 10:08

MOT test number

915948870814

Result

✗ Failed

Advice

Offside Rear Outer Tyre slightly damaged/cracking or perishing Outer sidewall perishing. (5.2.3 (d) (ii))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MAJOR

Offside Front Direction indicator not working (4.4.1 (a) (ii))

MAJOR

Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Nearside Rear Outer Tyre slightly damaged/cracking or perishing Outer sidewall perishing . (5.2.3 (d) (ii))

MAJOR

Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MAJOR

Offside Front Position lamp not working (4.2.1 (a))

MAJOR

Offside Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #10**

2018-08-20 10:59

MOT test number

513219516762

Result**✗ Failed****MAJOR** Offside Headlamp aim too high (4.1.2 (a))**Advice** Rear reverse lamps not working**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Offside Headlamp insecure (4.1.1 (c))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))**DANGEROUS** Nearside Front Tyre has ply or cords exposed outer wall damaged (5.2.3 (d) (ii))**MOT #9**

2017-09-01 14:02

MOT test number

840098870596

Result**✓ Passed****Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside headlight low (on limit)**Advice** N/s/r and o/s/r tyres side wall cracked**MOT #8**

2015-12-10 12:07

MOT test number

500422271519

Result**✓ Passed****MOT #7**

2014-11-25 14:11

MOT test number

516129824387

Result**✓ Passed**

**MOT #6** 2013-12-06 09:53**MOT test number** 435840443317**Result** ✓ Passed**Notice** No smoke meter reading detected**Notice** N/s/r tyre perished**MOT #5** 2012-11-26 15:24**MOT test number** 699321032353**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-12-08 12:19**MOT test number** 598342441378**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2010-12-10 15:16**MOT test number** 130944540374**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front Direction indicators slightly discoloured (1.4.A.2f)



MOT #2	2009-12-02 15:53
MOT test number	422886039424
Result	✓ Passed
Advice	Front Direction indicators slightly discoloured (1.4.A.2f)
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #1	2008-07-14 08:28
MOT test number	434066998126
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
13 September 2024

Tax status		Valid until 1 October
Days left		156
MOT expiry date		13 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-07-11
Last registration	2023-09-14
Complete history	See info



Registration #1	2005-07-11	26 mi
Registration #2	2008-07-14	31.935 mi
Registration #3	2009-12-02	44.847 mi
Registration #4	2010-12-10	48.470 mi
Registration #5	2011-12-08	59.778 mi
Registration #6	2012-11-26	65.901 mi
Registration #7	2013-12-06	68.487 mi
Registration #8	2014-11-25	71.070 mi
Registration #9	2015-12-10	73.375 mi
Registration #10	2017-09-01	75.167 mi
Registration #11	2018-08-20	76.308 mi
Registration #12	2019-05-20	76.308 mi
Registration #13	2019-05-20	76.308 mi
Registration #14	2019-05-20	76.308 mi
Registration #15	2019-05-20	76.308 mi
Registration #16	2019-05-20	76.308 mi
Registration #17	2019-05-20	76.308 mi
Registration #18	2019-05-20	76.308 mi
Registration #19	2019-05-20	76.308 mi
Registration #20	2019-05-20	76.308 mi
Registration #21	2019-05-20	76.308 mi
Registration #22	2019-05-20	76.308 mi

More info >



Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	DZ354029760