



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Black
Year of manufacture	2004
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 2

Date	2023-12-12
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-07-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-25
MOT pass rate	68 %
MOT passed	17
Failed MOT tests	8
Total advice items	73
Total items failed	19

MOT #25	2024-03-25 16:47
---------	------------------

MOT test number	705772595890
-----------------	--------------

Result	✗ Failed
MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR Position lamp has a product on the lens or light source which shows white light to the rear damaged (4.2.3 (b) (ii))	
MAJOR Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))	
Advice	Tie bars corroded underside
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush debonding (5.3.4 (a) (i))
Minor	Nearside Front Tyre obviously under inflated (5.2.3 (l))

**MOT #24**

2023-04-24 10:27

MOT test number

542898188184

Result

✓ Passed

- Advice** Rear both strengthening bars corroded
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Nearside Front outer sill corroded

MOT #23

2022-04-22 10:01

MOT test number

175376240357

Result

✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated seeping (6.1.7 (g) (i))
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Minor** Drive shaft joint constant velocity boot severely deteriorated seeping (6.1.7 (g) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #22**

2022-04-22 10:01

MOT test number

929389558130

Result

✗ Failed

Minor Drive shaft joint constant velocity boot severely deteriorated seeping (6.1.7 (g) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated seeping (6.1.7 (g) (i))**Pass with rectification** Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #21**

2021-04-26 10:38

MOT test number

174383588784

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases front exhaust (6.1.2 (a))**MOT #20**

2019-06-26 11:10

MOT test number

123252496280

Result

✓ Passed

Advice Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2018-06-20 10:00

MOT test number

870265499659

Result

✓ Passed

Advice

Both front tyres at 3mm

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18

2017-06-21 11:57

MOT test number

239578006792

Result

✓ Passed

Advice

Front tyres cracking

Advice

EML on

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Under tray broken and hanging low

MOT #17

2017-06-10 08:05

MOT test number

712648406897

Result

✗ Failed

Advice

EML on

Advice

Under tray broken and hanging low

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Front tyres cracking

Fail

Nearside Side repeater not working (1.4.A.2c)

**MOT #16**

2016-06-06 12:49

MOT test number

405885830078

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Engine light on**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #15**

2016-06-06 09:14

MOT test number

270574145870

Result

✗ Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Engine light on**MOT #14**

2015-06-17 10:38

MOT test number

876898065120

Result

✓ Passed

Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #13** 2015-06-17 10:38**MOT test number** 855048265126**Result** ✗ Failed**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #12** 2014-06-25 15:57**MOT test number** 926226674176**Result** ✓ Passed**MOT #11** 2013-05-23 12:00**MOT test number** 657433443133**Result** ✓ Passed**MOT #10** 2013-05-22 12:19**MOT test number** 565722943155**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Engine light on low water light on**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Brake pedal spongy (3.3.B.1b)**MOT #9** 2012-05-24 13:29**MOT test number** 907255742162**Result** ✓ Passed**Notice** Oil Light Flashing**Notice** Both Front Brake Discs Corroded but not considered Excessive**Notice** Engine Management Light On



MOT #8 2011-04-21 10:56

MOT test number 969881011157

Result ✓ Passed

- Notice** Nail in nearside rear tyre
- Notice** EML on
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Nail in offside rear tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2011-04-21 10:56

MOT test number 847701011151

Result ✗ Failed

- Notice** Nail in offside rear tyre
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Nail in nearside rear tyre
- Notice** EML on
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2010-04-26 17:20

MOT test number

883076810180

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Notice** Engine management light on.**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Notice** Nail in offside rear tyre**MOT #5**

2010-04-26 12:17

MOT test number

283046610143

Result

✗ Failed

Fail Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Rear Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Notice** Engine management light on.**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Rear Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Notice** Nail in offside rear tyre



MOT #4	2009-04-16 09:33
MOT test number	881826809127
Result	✓ Passed
Notice	Both rear tyres perished - advise replacement
Notice	Air bag warning light on

MOT #3	2008-04-18 14:43
MOT test number	123549808161
Result	✓ Passed

MOT #2	2007-04-13 13:12
MOT test number	271863407406
Result	✓ Passed

MOT #1	2007-03-14 16:47
MOT test number	563163077086
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✗
MOT

Expired:
25 April 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	25 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-03-11
Last registration	2024-03-25
Complete history	See info



Registration #1	2004-03-11	26 mi
Registration #2	2007-03-14	25.260 mi
Registration #3	2007-04-13	25.663 mi
Registration #4	2008-04-18	32.191 mi
Registration #5	2009-04-16	37.219 mi
Registration #6	2010-04-26	47.263 mi
Registration #7	2010-04-26	47.265 mi
Registration #8	2011-04-21	52.805 mi
Registration #9	2012-05-24	59.288 mi
Registration #10	2013-05-22	65.538 mi
Registration #11	2013-05-23	65.550 mi
Registration #12	2014-06-25	74.643 mi
Registration #13	2015-06-17	76.694 mi
Registration #14	2016-06-20	76.777 mi
Registration #15	2017-06-20	76.777 mi
Registration #16	2018-06-20	76.777 mi
Registration #17	2019-06-20	76.777 mi
Registration #18	2020-06-20	76.777 mi
Registration #19	2021-06-20	76.777 mi
Registration #20	2022-06-20	76.777 mi
Registration #21	2023-06-20	76.777 mi
Registration #22	2024-03-25	76.777 mi
Registration #23		
Registration #24		
Registration #25		



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1918 mm
Height	1502 mm
Length	4081 mm
Wheel base	2509 mm
Kerb weight	1385 kg
Max. allowed weight	1757 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS 028535