






report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX GHIA TDCI EU4
Colour	Blue
Year of manufacture	2007
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	321 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2021-08-16
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	5
Total items failed	14

MOT #15	2020-08-17 12:54
MOT test number	216293004160
Result	✓ Passed
Next expiry date	2021-08-16

MOT #14	2019-06-25 09:56
MOT test number	152983645007
Result	✓ Passed

MOT #13	2019-06-21 07:27
MOT test number	163553973154
Result	× Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT #12 2018-06-18 08:02 325804862772 **MOT** test number ✓ Passed Result **Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

 MOT #11
 2017-06-12 07:01

 MOT test number
 314505704681

 Result
 ✓ Passed

MOT test number

Result

Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail

Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

Fail

Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #9

MOT test number

100320153126

Result

✓ Passed

 MOT #8
 2015-03-25 08:50

 MOT test number
 139214685476

 Result
 ✓ Passed

CarCheck.co.uk page 3/12



MOT test number

Result

CarCheck.co.uk

EK07UVY

report date: 2024-03-28

367159282036

✓ Passed

page 4/12

MOT test number

Result

Fail Nearside Rear Seat belt retracting mechanism defective (5.2.5b)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

MOT #6 2014-04-05 12:57 185915694042 **MOT** test number Result ✓ Passed 2014-04-05 12:13 **MOT #5** 178875094410 **MOT** test number Result × Failed Fail Registration plate lamp not working (1.1.C.1d) Fail Nearside Rear Tyre fouling a part of the vehicle (4.1.D.2) Nearside Front passanger door cannot be enough from incide the vehicle (6.2 R.1h)

Fall	Nearside Front passenger door cannot be opened from inside the vehicle (6.2.8.1b)	
Fail	Offside Front Front position lamp(s) not working (1.1.A.3b)	
MOT #	4	2013-03-30 17:31
MOT t	est number	985489183094
Result		✓ Passed
MOT #	3	2012-03-29 09:44



Result

EKO7UVY report date: 2024-03-28

✓ Passed

 MOT #2
 2011-03-21 10:33

 MOT test number
 646950181055

 Result
 ✓ Passed

 MOT #1
 2010-03-22 15:18

 MOT test number
 164201680097

CarCheck.co.uk page 5/12



EKO7UVY report date: 2024-03-28

See MOT history

Tax & MOT check



X MOT

Expired: 16 August 2021

Tax expired: 27 January 2021

Tax status	Expired at 27 January 2021
Days left	1188 days too late
MOT expiry date	16 August 2021

Tax calculation

Full MOT history

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



EKO7UVY
report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



EKO7UVY report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	biotom
UMMINAI	nisiaiv
OVVIICI	IIIJCOI Y

o met metery	
For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	

THE STREET STREE	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK NEZ
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 9/12



EKO7UVY report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-03-19
Last registration	2020-08-17
Complete history	See info



Registration #1	2007-03-19	19 mi
Registration #2	2010-03-22	24.795 mi
Registration #3	2011-03-21	38.995 mi
Registration #4	2012-03-29	51.201 mi
Registration #5	2013-03-30	64.289 mi
Registration #6	2014-04-05	76.391 mi
Registration #7	2014-04-05	76.391 mi
Registration #8	2015-03-24	87.546 mi
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		11.777 mi
Registration #14		0.00 44
Registration #15		0.074
Registration #16		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1544 kg
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12

Number of axles2Engine number7D17452