



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	White
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	175 g/km
CO2 label	H







Internet history

Entry 2

Date	2021-12-03
Pictures	39
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-22
Pictures	17
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-10-22
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	23
Total items failed	11

MOT #14	2023-10-23 15:14
MOT test number	975391270926
Result	✓ Passed
Next expiry date	2024-10-22

MOT #13	2022-10-21 16:30
MOT test number	455888316916
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2022-10-21 16:30

MOT test number

516516894135

Result

✗ Failed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2021-10-22 12:02

MOT test number

667209131302

Result

✓ Passed

MOT #10

2021-04-14 09:22

MOT test number

115017301470

Result

✓ Passed

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #9**

2021-04-13 08:15

MOT test number

820904570180

Result**✗ Failed****Fail**

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8

2020-03-31 11:48

MOT test number

301684490056

Result**✓ Passed****Advice**

Chip in screen

MOT #7

2020-03-30 14:32

MOT test number

204390344625

Result**✗ Failed****Fail**

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Chip in screen

Advice

Offside Rear Nail in tyre

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #6** 2019-04-18 14:41**MOT test number** 266454326248**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Coolant leak**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-04-28 12:05**MOT test number** 215393059069**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2018-04-27 08:30**MOT test number** 575332429385**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2017-03-11 11:46**MOT test number** 599981174827**Result** ✓ Passed**MOT #2** 2016-02-15 12:35**MOT test number** 696471792395**Result** ✓ Passed



MOT #1	2015-02-12 12:18
MOT test number	308753945035
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-06-29
Current registration	 XXXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-03-01
Last registration	2023-10-23
Complete history	See info



Registration #1	2012-03-01	14 mi
Registration #2	2015-02-12	12.047 mi
Registration #3	2016-02-15	18.528 mi
Registration #4	2017-03-11	25.688 mi
Registration #5	2018-04-27	33.813 mi
Registration #6	2018-04-28	33.813 mi
Registration #7	2019-04-18	38.851 mi
Registration #8	2020-03-30	50.109 mi
Registration #9	2020-03-31	50.109 mi
Registration #10	2020-03-31	50.109 mi
Registration #11	2020-03-31	50.109 mi
Registration #12	2020-03-31	50.109 mi
Registration #13	2020-03-31	50.109 mi
Registration #14	2020-03-31	50.109 mi
Registration #15	2020-03-31	50.109 mi
Registration #16	2020-03-31	50.109 mi
Registration #17	2020-03-31	50.109 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	145854K