



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX
Colour	Blue
Year of manufacture	2014
Top speed	121 mph
0 - 100 km/h	10.2 seconds
Gearbox	6 speed manual

Engine & fuel consumption

Power	103 kW / 140 HP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	50.0 mpg
Consumption combined	44.4 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-27
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-15
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	28
Total items failed	2

MOT #10	2023-12-16 15:38
---------	------------------

MOT test number	180720376370
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-12-15
------------------	------------

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2023-12-09 16:46

MOT test number

967963368087

Result

✗ Failed

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps both not working.
(4.7.1 (b) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
(5.3.4 (a) (i))

Advice Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MAJOR Offside Front Service brake excessively fluctuating (1.2.1 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
(5.3.4 (a) (i))

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MAJOR Rear Exhaust system insecure mount broken. (6.1.2 (a))

MAJOR Nearside Front Service brake excessively fluctuating (1.2.1 (e))

MOT #8

2022-11-26 10:49

MOT test number

453174798297

Result

✓ Passed

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #7

2021-11-26 16:28

MOT test number

704649851413

Result

✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6

2020-11-30 16:46

MOT test number

846693838919

Result

✓ Passed

**MOT #5** 2019-11-22 09:17**MOT test number** 357086358593**Result** ✓ Passed**Advice** Item in swept area not materially affecting view of the road but advise moving for obvious reasons**MOT #4** 2019-11-15 09:56**MOT test number** 844680754149**Result** ✗ Failed**Advice** Item in swept area not materially affecting view of the road but advise moving for obvious reasons**MAJOR** Nearside Rear Body component damaged and likely to cause injury door trim (6.2.1 (a) (i))**MOT #3** 2018-11-16 09:21**MOT test number** 698534662357**Result** ✓ Passed**Advice** Offside Rear Tyre outer sidewall perished**Advice** Offside Front Alloy has damage on inner rim**Advice** Rear Brake pads very low and brake discs worn**Advice** Exhaust system and hangars very corroded**Advice** Nearside Rear Door has damage to trim**Advice** Front Brake pads getting low**MOT #2** 2017-11-22 11:18**MOT test number** 183587165978**Result** ✓ Passed



MOT #1	2017-11-22 09:55
MOT test number	515520391230
Result	✗ Failed
Fail	Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' phone holder/object (8.3.1e)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm 225/50/17 (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit advise renewing (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 December 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LK64UZC
Plate since	2024-03-29
Current registration	LK64UZC
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-11-29
Last registration	2023-12-16
Complete history	See info



Registration #1	2014-11-29	9 mi
Registration #2	2017-11-22	35.827 mi
Registration #3	2017-11-22	35.827 mi
Registration #4	2018-11-16	44.118 mi
Registration #5	2019-11-15	53.545 mi
Registration #6	2019-11-22	53.742 mi
Registration #7	2019-11-22	53.742 mi
Registration #8	2019-11-22	53.742 mi
Registration #9	2019-11-22	53.742 mi
Registration #10	2019-11-22	53.742 mi
Registration #11	2019-11-22	53.742 mi
Registration #12	2019-11-22	53.742 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1590 kg

Additional information

Fuel tank capacity	70 l
Number of axles	2
Engine number	EA09685