



report date: 2024-03-28

General information

Make	AUDI
Model	A2 FSI SE
Colour	Blue
Year of manufacture	2004
Top speed	126 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	155 Nm at 4.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	60.1 mpg
Consumption extra urban	34.9 mpg
Consumption combined	47.9 mpg
CO2 emission	142 g/km
CO2 label	F







Internet history

Entry 2


Date	2021-07-20
Pictures	29
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-07
Pictures	29
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-07-12
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	22
Total items failed	6

MOT #23	2023-07-06 09:28
MOT test number	309892137002
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22	2023-07-04 08:48
MOT test number	360455724178
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #21	2022-07-11 11:47
MOT test number	867254592701
Result	✓ Passed
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20** 2022-07-11 10:52**MOT test number** 275430134014**Result** ✗ Failed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #19** 2021-07-13 15:16**MOT test number** 321769406015**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #18** 2020-08-25 07:51**MOT test number** 633876920848**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #17** 2019-05-29 10:26**MOT test number** 610898307338**Result** ✓ Passed**MOT #16** 2018-06-14 16:12**MOT test number** 819869345964**Result** ✓ Passed

**MOT #15** 2018-06-14 11:53**MOT test number** 442909660383**Result** ✗ Failed**MAJOR** Rear Service brake excessively binding both sides (1.2.1 (f))**DANGEROUS** Offside Stop lamp(s) all not working (4.3.1 (a) (iii))**MOT #14** 2017-06-19 10:05**MOT test number** 664362722352**Result** ✓ Passed**MOT #13** 2017-06-19 10:05**MOT test number** 627337940551**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #12** 2016-06-15 11:57**MOT test number** 394311633076**Result** ✓ Passed**MOT #11** 2016-06-15 09:22**MOT test number** 458930741229**Result** ✗ Failed**Fail** Front Anti-roll bar linkage has excessive play in a ball joint both sides (2.4.G.2)**MOT #10** 2015-06-10 15:01**MOT test number** 957421265146**Result** ✓ Passed**Notice** Front fog light switch broken, lights stay on all the time

**MOT #9** 2015-06-09 11:44**MOT test number** 797190765177**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Front fog light switch broken, lights stay on all the time**MOT #8** 2014-06-11 09:50**MOT test number** 847722864107**Result** ✓ Passed**Notice** Front fog lights not switching off**MOT #7** 2013-06-03 08:43**MOT test number** 775104653116**Result** ✓ Passed**MOT #6** 2012-06-06 10:56**MOT test number** 237038352131**Result** ✓ Passed**MOT #5** 2011-06-06 08:52**MOT test number** 587817851114**Result** ✓ Passed**Notice** Rear discs very rusty**MOT #4** 2010-06-03 11:46**MOT test number** 841314050167**Result** ✓ Passed**Advice** Rear brake disc slightly pitted (3.5.1h)



MOT #3	2009-05-14 12:56
MOT test number	320684139183
Result	✓ Passed
Notice	Rear discs corroded

MOT #2	2008-05-14 09:24
MOT test number	853645638112
Result	✓ Passed

MOT #1	2008-05-14 09:24
MOT test number	250795738433
Result	✗ Failed
Pass with rectification	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Pass with rectification	Offside Front Headlamp insecure (1.7.3)
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2023

✓

MOT

Expires:  
12 July 2024

Tax status	Expired at 1 April 2023
Days left	394 days too late
MOT expiry date	12 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-09-04
Last registration	2023-07-06
Complete history	<a href="#">See info</a>



Registration #1	2004-09-04	24 mi
Registration #2	2008-05-14	16.263 mi
Registration #3	2009-05-14	20.575 mi
Registration #4	2010-06-03	25.214 mi
Registration #5	2011-06-06	28.808 mi
Registration #6	2012-06-06	33.113 mi
Registration #7	2013-06-03	36.492 mi
Registration #8	2014-06-11	39.998 mi
Registration #9	2015-06-09	43.170 mi
Registration #10	2015-06-10	43.182 mi
Registration #11	2016-06-15	47.375 mi
Registration #12	2016-06-15	47.378 mi
Registration #13	2017-06-19	51.086 mi
Registration #14	2018-06-20	55.277 mi
Registration #15	2019-06-20	59.277 mi
Registration #16	2020-06-20	63.277 mi
Registration #17	2021-06-20	67.277 mi
Registration #18	2022-06-20	71.277 mi
Registration #19	2023-06-20	75.277 mi
Registration #20	2024-06-20	79.277 mi
Registration #21	2025-06-20	83.277 mi
Registration #22	2026-06-20	87.277 mi
Registration #23	2027-06-20	91.277 mi
Registration #24	2028-06-20	95.277 mi
Registration #25	2029-06-20	99.277 mi



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1553 mm
Length	3826 mm
Wheel base	2405 mm
Kerb weight	995 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	BAD 012000