





report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 280
Colour	Black
Year of manufacture	2006
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	300 Nm at 3.500 rpm
Engine capacity	2.996 cc
Cylinders	6
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	38.2 mpg
Consumption combined	29.7 mpg
CO2 emission	222 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry 1


Date 2021-08-07

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-14
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	21
Total items failed	4

MOT #18	2024-04-10 13:05
MOT test number	898682985199
Result	✓ Passed
Next expiry date	2025-04-14
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.	1.11 (c))

MOT #17		2023-04-15 11:17
MOT test	number	842201606243
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2023-04-15 10:23
MOT test number	145549776356
Result	× Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



FV56PZC

report date: 2024-03-29

MOT test number

Result

Advice
Centre exhaust mounting brackets missing

Advice
Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14

MOT test number

848923611985

Result

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Lower Suspension arm ball joint excessively worn as marked (5.3.4 (a) (i))

Advice Centre exhaust mounting brackets missing

MOT #13 2021-03-23 16:14 **MOT** test number 701210711596 Result Passed **MOT #12** 2019-12-13 10:11 **MOT** test number 370578351706 Result Passed **Advice** Undertrays and engine covers fitted **Advice** Rear Service brake fluctuating, but not excessively Both (1.2.1 (e))

MOT #11

MOT test number

Result

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Under-trays fitted obscuring some components

CarCheck.co.uk page 4/13



MOT #10 2017-11-20 11:57

MOT test number 947387440396

Advice Undertrays and engine covers fitted

MOT #9 2016-12-15 11:39

MOT test number 543776908577

Result
✓ Passed

Advice Undertrays and engine cover fitted

MOT #8 2015-12-10 11:08

MOT test number 335940526108

Result \sqrt{Passed}

MOT #7 2014-12-17 15:05

MOT test number 389011654313

Result \(\sqrt{Passed} \)

MOT #6 2014-12-17 15:05

MOT test number 686111554382

Result X Failed

Pass with rectification Offside Front Headlamp aim too high (1.8)

Pass with rectification Nearside Front Headlamp aim too high (1.8)

MOT #5 2013-11-22 13:19

MOT test number 197726523378

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/13



MOT #4 2012-12-08 10:13

MOT test number 705673442332

Result ✓ Passed

Notice Both side rear rtyres are worn to approx 3-3.5mm

Advice Offside Brake pipe slightly corroded (3.6.B.2c)

Notice Under-trays fitted obscuring some underside components

MOT #3 2011-11-25 09:14

MOT test number 139339621333

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2010-11-19 14:45

MOT test number 414273220375

Result ✓ Passed

MOT #1 2009-12-12 09:23

MOT test number 364416949389

Result
✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Type

Date

Damage 2

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-12-15
Last registration	2024-04-10
Complete history	See info



Registration #1	2006-12-15	15 mi
Registration #2	2009-12-12	14.407 mi
Registration #3	2010-11-19	27.410 mi
Registration #4	2011-11-25	32.388 mi
Registration #5	2012-12-08	33.963 mi
Registration #6	2013-11-22	35.413 mi
Registration #7	2014-12-17	38.194 mi
Registration #8	2015-12-10	41.272 mi
Registration #9	2016-12-15	44.231 mi
Registration #10	2017-11-20	46.385 mi
Registration #11		11.177 es
Registration #12		71.777 es
Registration #13		71.777 es
Designation #14		
Registration #14		11.117 au
Registration #15		11.777 es
-		11.777 es
Registration #15		11.777 es 11.777 es 11.777 es
Registration #15 Registration #16		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



		_		
- I) Im	ension	с Х.	WAIG	nt.
	CHSIUH	3 W	weiu	III.

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1460 kg
Max. allowed weight	1755 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27294230319669

CarCheck.co.uk page 13/13