





report date: 2024-03-28

General information

Make	FIAT
Model	500C LOUNGE
Colour	Grey
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	131 Nm at 4.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-04
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	10
Total items failed	5

MOT #15		2024-04-05 10:55
MOT test	number	214945827651
Result		✓ Passed
Next expi	ry date	2025-04-04
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14	2024-03-26 10:09
MOT test number	751442756289
Result	X Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3	3 (e))
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #13	2023-03-20 14:19
MOT test number	195374732805
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #12 2022-03-21 11:43

MOT test number 168871702666

Result
✓ Passed

MOT #11 2021-04-01 15:40

MOT test number 604907067607

Result ✓ Passed

MOT #10 2021-04-01 15:40

MOT test number 460822163976

Result X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #9 2020-08-08 11:29

MOT test number 934121808354

Result \rightarrow Passed

MOT #8 2020-08-08 11:29

MOT test number 842952400303

Result X Failed

Pass with rectification Nearside Front Headlamp aim projected beam image is obviously incorrect

(4.1.2 (c))

MOT #7 2019-08-09 14:36

MOT test number 129819990321

Result \sqrt{Passed}

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge devoid of tread (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge devoid of tread (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6		2019-08-09 13:37
MOT test	number	394962132081
Result		× Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge dev	void of tread (5.2.3 (e))
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Items removed from driver's view prior to test objects hanging from inte	erior mirror
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge d	evoid of tread (5.2.3 (e))
Fail C	Offside Headlamp aim not tested (4.1.2 (b))	

Fail Offside Headlamp aim not tested (4.1.2 (b))	
MOT #5	2018-01-09 13:27
MOT test number	983050455476
Result	✓ Passed
MOT #4	2017-01-07 11:03
MOT test number	359181986664
Result	✓ Passed
MOT #3	2016-01-11 11:48
MOT test number	468014339703
Result	✓ Passed
MOT #2	2015-01-28 11:07
MOT test number	578208625009
Result	✓ Passed
MOT #1	2014-01-15 14:19
MOT test number	868685214004

MOT #1	2014-01-15 14:19
MOT test number	868685214004
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

LP60PVX

report date: 2024-03-28

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT ha Check it in the premium report and see all owner registrations. Download the full report <u>here</u> .	ve?

THE STATE OF THE S	

More info	> >
Plate changes	

See in this check if this FIAT had different number plates.

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-01-31
Last registration	2024-04-05
Complete history	See info



Registration #1	2011-01-31	23 mi
Registration #2	2014-01-15	3.300 mi
Registration #3	2015-01-28	4.528 mi
Registration #4	2016-01-11	5.526 mi
Registration #5	2017-01-07	6.088 mi
Registration #6	2018-01-09	7.330 mi
Registration #7	2019-08-09	14.103 mi
Registration #8	2019-08-09	14.103 mi
Registration #9	2020-08-08	21.241 mi
1109.011.011		
Registration #10		11.777 es
		11.777 es
Registration #10		11.777 es 11.777 es 11.777 es
Registration #10 Registration #11		11.777-00 11.777-00 11.777-00 11.777-00
Registration #10 Registration #11 Registration #12		11.777-00 11.777-00 11.777-00 11.777-00
Registration #10 Registration #11 Registration #12 Registration #13		11 777 46 11 777 46 11 777 46 11 777 46 11 777 46
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		10 1777 466 20 1777 466 20 1777 466 20 1777 466 20 1777 466 20 1777 466

 $\quad \text{More info} \ \ >$

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

1647386