



Mercedes-Benz

KRI4TZE

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	CLS CLS250 CDI BLUEEFFICIENCY AMG SPORT
Colour	Black
Year of manufacture	2014
Top speed	150 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	138 g/km
CO2 label	E







Internet history

Entry 1

Date	2022-02-09
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-09-26
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #8	2023-09-27 15:54
MOT test number	217130093583
Result	✓ Passed
Next expiry date	2024-09-26

MOT #7	2022-08-22 10:57
MOT test number	446616506154
Result	✓ Passed

MOT #6	2022-08-17 11:06
MOT test number	683154666076
Result	✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #5	2021-07-28 13:45
MOT test number	796167689883
Result	✓ Passed

**MOT #4** 2020-07-28 11:24**MOT test number** 676625178798**Result** ✓ Passed**MOT #3** 2019-07-26 15:32**MOT test number** 907469823826**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2018-07-26 16:16**MOT test number** 547648701974**Result** ✓ Passed**MOT #1** 2017-05-27 15:32**MOT test number** 818867927749**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
26 September 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From
Owner	From
Owner	From
Owner	From
Owner	From
Owner	From

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 KR14TZE
Plate since	2024-03-28
Current registration	 KR14TZE
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-05-27
Last registration	2023-09-27
Complete history	See info



Registration #1	2014-05-27	20 mi
Registration #2	2017-05-27	26.346 mi
Registration #3	2018-07-26	33.634 mi
Registration #4	2019-07-26	37.848 mi
Registration #5	2020-07-28	43.322 mi
Registration #6	2021-05-27	50.000 mi
Registration #7	2022-05-27	55.000 mi
Registration #8	2023-05-27	60.000 mi
Registration #9	2023-09-27	65.000 mi
Registration #10	2023-09-27	65.000 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1881 mm
Height	1416 mm
Length	4940 mm
Wheel base	2874 mm
Kerb weight	1785 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	59 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	65192432196048