



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 DCI 115 PV LWB LC
Colour	Yellow
Year of manufacture	2007
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-01
Pictures	22
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-20
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	57
Total items failed	25

MOT #22	2023-07-03 14:31
MOT test number	124721734313
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #21	2023-07-03 14:01
MOT test number	201088023534
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #20** 2022-07-21 14:35**MOT test number** 231689809972**Result** ✓ Passed

**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning tail light not working marker lamp fitted to side of van (4.2.1 (a) (i))

**Advice** Offside drivers seat stiff to move

**Advice** Central Front exhaust flexi pipe slight blow and cracking

**MOT #19** 2022-07-14 11:10**MOT test number** 219833596873**Result** ✗ Failed

**Advice** Central Front exhaust flexi pipe slight blow and cracking

**Advice** Offside drivers seat stiff to move

**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning tail light not working marker lamp fitted to side of van (4.2.1 (a) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #18** 2021-07-17 05:55**MOT test number** 757068195848**Result** ✓ Passed

**MOT #17**

2021-07-09 08:28

**MOT test number**

784863032847

**Result****✗ Failed**

- Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #16**

2021-02-08 11:46

**MOT test number**

263332131422

**Result****✓ Passed**

- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))

**MOT #15**

2021-02-02 16:45

**MOT test number**

882390640448

**Result****✗ Failed**

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #14**

2019-11-19 13:08

**MOT test number**

649654895242

**Result****✓ Passed**

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Rear Brake pipe corroded, covered in grease or other material \* 2 (1.1.11 (c))

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #13**

2018-07-17 14:37

**MOT test number**

582500634801

**Result**

✓ Passed

**Advice** Play in steering rack inner joint(s)**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #12**

2018-07-17 14:37

**MOT test number**

622007684425

**Result**

✗ Failed

**Advice** Play in steering rack inner joint(s)**Pass with rectification** Hazard warning switch inoperative (4.4.2 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11**

2017-07-13 16:02

**MOT test number**

436360142968

**Result**

✓ Passed

**Advice** Edge of nearside windscreen cracked not affecting drivers view**MOT #10**

2017-07-13 16:02

**MOT test number**

249518899243

**Result**

✗ Failed

**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Edge of nearside windscreen cracked not affecting drivers view



MOT #9	2015-12-09 10:32
MOT test number	223751962746
Result	✓ Passed

MOT #8	2014-06-04 15:49
MOT test number	455375554177
Result	✓ Passed
Advice	Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
Notice	Oil leak
Advice	Offside Brake pipe slightly corroded (3.6.B.2c)
Notice	No spare wheel



**MOT #7**

2014-05-30 09:55

**MOT test number**

955350554184

**Result****✗ Failed**

- Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Notice** Oil leak
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Headlamp aim too high (1.8)
- Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Fail** Centre Stop lamp not working (1.2.1b)
- Notice** No spare wheel
- Fail** Offside Headlamp aim too high (1.8)

**MOT #6**

2013-06-07 17:19

**MOT test number**

257408053178

**Result****✓ Passed**

- Notice** Front and rear discs are liped
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #5** 2013-06-05 10:19**MOT test number** 977266153185**Result** ✗ Failed**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Front and rear discs are lipped**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #4** 2012-05-31 09:21**MOT test number** 687762852115**Result** ✓ Passed**MOT #3** 2012-05-31 09:21**MOT test number** 175222552104**Result** ✗ Failed**Pass with rectification** Nearside Front wheel bearing has excessive play (2.5.A.3c)**MOT #2** 2011-06-04 09:54**MOT test number** 535825951160**Result** ✓ Passed**MOT #1** 2010-06-04 15:51**MOT test number** 164185450134**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 July 2024

<b>Tax status</b>	Valid until 1 September
-------------------	-------------------------

<b>Days left</b>	124
------------------	-----

<b>MOT expiry date</b>	20 July 2024
------------------------	--------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-06-05
Last registration	2023-07-03
Complete history	<a href="#">See info</a>



Registration #1	2007-06-05	16 mi
Registration #2	2010-06-04	59.868 mi
Registration #3	2011-06-04	83.115 mi
Registration #4	2012-05-31	110.338 mi
Registration #5	2013-06-05	137.277 mi
Registration #6	2013-06-07	137.277 mi
Registration #7	2014-05-30	161.136 mi
Registration #8	2014-06-04	161.136 mi
Registration #9	2015-12-09	511 mi
Registration #10	2017-07-13	13.921 mi
Registration #11	2017-07-13	13.921 mi
Registration #12	2018-07-17	18.453 mi
Registration #13	2019-06-05	25.277 mi
Registration #14	2019-06-05	25.277 mi
Registration #15	2019-06-05	25.277 mi
Registration #16	2019-06-05	25.277 mi
Registration #17	2019-06-05	25.277 mi
Registration #18	2019-06-05	25.277 mi
Registration #19	2019-06-05	25.277 mi
Registration #20	2019-06-05	25.277 mi
Registration #21	2019-06-05	25.277 mi
Registration #22	2019-06-05	25.277 mi
Registration #23	2019-06-05	25.277 mi

More info >





Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Height	1944 mm
Length	5182 mm

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C094559