





report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA D-4D COLOUR COLLECTION
Colour	Blue
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	190 Nm at 1.800 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 3

Date 2022-01-06

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk


Entry 2

Date	2021-12-06
------	------------

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-10-16

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-19
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	50
Total items failed	4

MOT #19	2024-01-02 16:17
MOT test number	468207560921
Result	✓ Passed
Next expiry date	2025-01-19
Advice Front Coil spring corroded both (5.3.1 (b) (i))	
Advice Rear Coil spring corroded both (5.3.1 (b) (i))	

MOT #18	2024-01-02 12:05
MOT test number	655660021896
Result	X Failed
Advice Front Coil spring corroded both (5.3.1 (b) (i))	
Advice Rear Coil spring corroded both (5.3.1 (b) (i))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #17	2023-01-09 11:04
MOT test number	226256488005
Result	✓ Passed
Advice Minor chip on wind screen	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #16 2022-01-07 13:21

MOT test number 369208918273

MOT #15 2021-01-06 12:44

MOT test number 292225651851

Advice Offside Front Tyre worn close to legal limit/worn on edge 195/60/15 advise new tyre soon (5.2.3)

(e))

Advice Central Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 195/60/15 advise new tyre soon (5.2.3

(e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Vehicle restricted view

MOT #14 2020-01-10 17:20

MOT test number 955051387979

Result

Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing and worn on inner and outer edge (5.2.3

(d) (ii))

Advice Engine under tray

Advice Nearside Front Tyre slightly damaged/cracking or perishing and worn on inner and outer edge

(5.2.3 (d) (ii))

Advice Engine bay restricted view

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #13 2020-01-10 12:19

MOT test number 686721803234

Result X Failed

Advice Offside Front Tyre slightly damaged/cracking or perishing and worn on inner and outer edge (5.2.3

(d) (ii))

Advice Engine under tray

Advice Nearside Front Tyre slightly damaged/cracking or perishing and worn on inner and outer edge

(5.2.3 (d) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit 0.80 (8.2.2.2 (a))

Advice Engine bay restricted view

MOT #12 2019-01-10 16:50

MOT test number 754410064306

Advice Offside Front tyre worn on inner and outer edge

Advice Engine under tray

Advice Nearside Front tyre worn on inner and outer edge

Advice Engine bay restricted view

MOT #11 2018-01-08 12:11

MOT test number 572186095904

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Wiper blade split

CarCheck.co.uk page 5/15



report date: 2024-03-28




MOT #9	2017-01-06 15:4
MOT test	number 47106840595
Result	✓ Passe
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Engine bay restricted view
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt child seat insecure
Advice	Engine under tray

MOT #8	2016-01-20 12:25
MOT test number	637372623502
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear seat belt not tested child seat	

CarCheck.co.uk page 6/15



report date: 2024-03-28



MOT #6		2015-01-14 13:15
MOT test	number	347224715001
Result		✓ Passed
Notice	Nearside rear child seat insecure	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Under-trays fitted obscuring some underside components	
Notice	Nearside rear seat belt not tested child seat	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #5		2013-11-06 09:55
MOT test	number	195930813388
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Damage on nearside front wing	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT test number

Some sult

Notice Advise o/s/r tyre on 3mm

Notice Advise n/s and o/s/f track rod end ball joint gators weeping

Notice Advise n/s/r tyre between 2-3mm

Notice Advise slight brake bind o/s/r

MOT #3		2011-11-15 13:39
MOT test	number	776909211352
Result		✓ Passed
MOT #2		2010-11-12 13:48
MOT test	number	111406310384
Result		✓ Passed
Advice	Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	

MOT #1	2009-11-19 15:38
MOT test number	504903829352
Result	✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	19 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

RF56LWZ

report date: 2024-03-28

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYO have? Check it in the premium report and see all owner registrations. Download the full report here .	DTA

Plate changes

See in this check if this TOYOTA had different number plates.	
Number of plates	,
Correct registration	New Park
Plate since	
Current registration	SIP.
Plate since	

More info >

More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-01-25
Last registration	2024-01-02
Complete history	See info



Registration #1	2007-01-25	13 mi
Registration #2	2009-11-19	22.633 mi
Registration #3	2010-11-12	30.130 mi
Registration #4	2011-11-15	35.600 mi
Registration #5	2012-10-29	41.624 mi
Registration #6	2013-11-06	45.613 mi
Registration #7	2015-01-14	51.569 mi
Registration #8	2016-01-19	55.359 mi
Registration #9	2016-01-20	55.359 mi
Registration #10	2017-01-06	58.438 mi
Registration #11	2018-01-08	62.873 mi
•	2018-01-08 2018-01-08	62.873 mi
Registration #11		
Registration #11 Registration #12	2018-01-08	
Registration #11 Registration #12 Registration #13	2018-01-08	
Registration #11 Registration #12 Registration #13 Registration #14	2018-01-08	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2018-01-08	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2018-01-08	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2018-01-08	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	2018-01-08	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	2018-01-08	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	2018-01-08	

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1250 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 15/15

Number of axles 2

Engine number 1ND0323907