





report date: 2024-03-28

## General information

Make	FORD
Model	TRANSIT 350 P/V
Colour	Silver
Year of manufacture	2013
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	123 BHP
Max. torque	350 Nm at 1.450 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	32.8 mpg
Consumption combined	29.4 mpg
CO2 emission	249 g/km
CO2 label	L



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

### Entry 2

Date 2022-01-03

Pictures 22

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

 Date
 2021-12-26

 Pictures
 23

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



WR13NVV
report date: 2024-03-28

MOT history

MOT expiry date	2025-03-17
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	23
Total items failed	4

MOT #11		2024-03-18 09:17
MOT test	number	524986280945
Result		✓ Passed
Next expi	ry date	2025-03-17
Advice	Offside Rear outer axle seal leaking oil	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material acr	oss axle (1.1.11 (c))
Advice	Advice Offside Front Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))	
Advice	Nearside Rear outer axle seal leaking oil	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material t	o flexi (1.1.11 (c))

MOT #10		2023-02-23 09:29
MOT test	number	282429165191
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c	:))
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))		c))
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

MOT #9	2022-02-18 15:59
MOT test number	494429508384
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

412878806554

Result

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice (a) (i))

**MOT #7** 2021-03-05 13:10 **MOT** test number 900360703147 Result × Failed **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT test number

Result

Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

(a) (i))

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4)

MOT #5

MOT test number

678070241773

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front tyre worn on inner edge

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2018-03-12 13:45

**MOT test number** 675865711457

MOT #3 2017-04-18 07:59

**MOT test number** 582067669724

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2016-05-16 11:21

**MOT test number** 541358769497

Result 

Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #1** 2016-05-13 08:36

MOT test number 392346586891

Result X Failed

**Advice** Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Nearside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/12



WR13NVV
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	17 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
*********	
***************************************	
***************************************	
*********	
*************	
Plate changes	More info >
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NA
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

## Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-22
Last registration	2024-03-18
Complete history	See info



Registration #1	2013-05-22	24 mi
Registration #2	2016-05-13	35.674 mi
Registration #3	2016-05-16	35.674 mi
Registration #4	2017-04-18	42.165 mi
Registration #5	2018-03-12	53.055 mi
Registration #6	2019-03-05	63.231 mi
Registration #7	2020-03-11	69.513 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



WR13NVV report date: 2024-03-28

Car features

The FORD factory car options list is only	y available in the premium report.
---	------------------------------------

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	

View the complete FORD factory list for this vehicle <u>here</u>.

More info >

# Safety ratings

**S0569** 

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1974 mm
Height	2397 mm
Length	5230 mm
Wheel base	3750 mm
Kerb weight	2098 kg
Max. allowed weight	3500 kg

## Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles CarCheck.co.uk	2 page 12/