



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	BOXER HDI 335 L3H2 PROFESSIONAL P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	37.6 mpg
Consumption combined	32.4 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-02-22
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	57
Total items failed	2

MOT #16 2024-02-13 15:59

MOT test number 535834746805

Result ✓ Passed

Next expiry date 2025-02-22

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Underbody corrosion

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15 2023-02-15 14:38

MOT test number 130083719972

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14**

2023-02-14 12:36

MOT test number

612769465529

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn most rear (5.3.4 (a) (i))
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn most rear (5.3.4 (a) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #13

2022-02-10 11:40

MOT test number

160923475267

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2022-02-09 11:41

MOT test number

620512599126

Result**✗ Failed**

- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #11

2021-02-23 15:39

MOT test number

982707751651

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2021-02-22 15:31

MOT test number

261393802093

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Offside Front Inner Steering linkage ball joint has excessive play tie bar (2.1.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Front Inner Steering linkage ball joint has excessive play tie bar (2.1.3 (b) (i))
- MAJOR** Horn not working (7.7 (a) (ii))

MOT #9

2019-06-25 14:32

MOT test number

503906965298

Result**✓ Passed**

- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #8** 2019-06-25 11:01**MOT test number** 664592591788**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Body component damaged and likely to cause injury mirror (6.2.1 (a) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**DANGEROUS** Offside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7** 2018-07-10 10:38**MOT test number** 979244294251**Result** ✓ Passed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #6** 2017-07-06 12:11**MOT test number** 537217517509**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-07-11 10:29**MOT test number** 536695914561**Result** ✓ Passed

**MOT #4** 2015-07-09 13:31**MOT test number** 947770895107**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-07-11 12:50**MOT test number** 849962694184**Result** ✓ Passed**MOT #2** 2014-07-11 12:50**MOT test number** 905132494186**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #1** 2013-07-10 14:31**MOT test number** 268901393157**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 February 2025

Tax status		Valid until 1 March
Days left		307
MOT expiry date		22 February 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YJ12SBO
Plate since	2024-03-28
Current registration	YJ12SBO
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-06-29
Last registration	2024-02-13
Complete history	See info



Registration #1	2012-06-29	6 mi
Registration #2	2013-07-10	15.513 mi
Registration #3	2014-07-11	34.662 mi
Registration #4	2015-07-09	48.528 mi
Registration #5	2016-07-11	64.303 mi
Registration #6	2017-07-06	77.314 mi
Registration #7	2018-07-10	91.994 mi
Registration #8	2019-06-25	111.753 mi
Registration #9	2020-06-25	131.513 mi
Registration #10	2021-06-25	151.273 mi
Registration #11	2022-06-25	171.033 mi
Registration #12	2023-06-25	190.793 mi
Registration #13	2024-02-13	210.553 mi
Registration #14		
Registration #15		
Registration #16		

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5998 mm
Kerb weight	2101 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	4H032705668