





report date: 2024-03-28

## General information

Make	FORD
Model	ECOSPORT ST-LINE
Colour	Silver
Year of manufacture	2018
Top speed	111 mph
0 - 100 km/h	12.7 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	92 kW / 125 HP / 123 BHP
Max. torque	170 Nm at 1.400 rpm
<b>Engine capacity</b>	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



YR18YNL

report date: 2024-03-28

# Internet history

#### Entry 3

Date 2021-06-30

Pictures 23

Listing price <u>View report</u>









#### source: heycar.co.uk

#### Entry 2

Date	2021-06-11
Pictures	22

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-05-30	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-18
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	18
Total items failed	0

MOT #5		2024-03-13 10:06
MOT test	number	987893900641
Result		✓ Passed
Next expi	ry date	2025-03-18
<b>Advice</b> (5.2.3 (e))	Offside Front Tyre worn close to legal limit/worn on edge Worn to 3mm and	l cracking/perished
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn to 3mm and cracking/perished (5.2.3 (e))		nd cracking/perished
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4		2023-03-10 13:58
MOT test	number	347633354053
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



**MOT #3** 2023-03-10 10:07

**MOT test number** 900215154335

**Result** ★ Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Slight interaction in n/s/r lamp

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #2 2022-03-18 17:03

**MOT test number** 368783885879

Result \( \sqrt{Passed} \)

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

**Advice** Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

**MOT #1** 2021-03-19 16:52

MOT test number 617986216918

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	18 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



YR18YNL

report date: 2024-03-28

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e mier metery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK NEW
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



YR18YNL

report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-20
Last registration	2024-03-13
Complete history	See info



Registration #1	2018-04-20	20 mi
Registration #2	2021-03-19	19.800 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	93%
Children	77%
Pedestrian	58%
Safety systems	55%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1713 mm
Length	4096 mm
Wheel base	2519 mm
Kerb weight	1280 kg
Max. allowed weight	1725 kg

# Additional information

Fuel tank capacity	52 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	nge 11/11

Number of axles 2
Engine number JJ67236