



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC PRIVILEGE DCI
Colour	Silver
Year of manufacture	2009
Top speed	119 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-14
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-30
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	50
Total items failed	8

MOT #18	2023-11-28 12:07
MOT test number	815228810416
Result	✓ Passed
Next expiry date	2024-11-30
Advice	Underbody covers fitted

MOT #17	2022-11-30 16:59
MOT test number	148146929541
Result	✓ Passed
Advice	BOTH SIDES REAR TYRES SLIGHTLY PRESHIED
Advice	BOTTOM ENGINE COVER FITTED OBSCURING SOME UNDERSIDE COMPONENTS

MOT #16	2022-11-29 14:04
MOT test number	976195521843
Result	✗ Failed
Advice	BOTH SIDES REAR TYRES SLIGHTLY PRESHIED
Fail	Brake performance not tested (1.2.1 (g))
Advice	BOTTOM ENGINE COVER FITTED OBSCURING SOME UNDERSIDE COMPONENTS
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #15** 2021-11-30 17:42**MOT test number** 301247957554**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both side (5.3.4 (a) (i))**MOT #14** 2020-11-25 11:48**MOT test number** 455145540647**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly damaged inner wing liner rubbing brake pipe and wear on pipe apparent (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin 80% worn (1.1.13 (a) (ii))**MOT #13** 2020-11-25 11:48**MOT test number** 381008801717**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin 80% worn (1.1.13 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Brake pipe slightly damaged inner wing liner rubbing brake pipe and wear on pipe apparent (1.1.11 (c))**MOT #12** 2019-11-29 16:30**MOT test number** 408798137146**Result** ✓ Passed

**MOT #11**

2019-11-29 12:26

MOT test number

131777925811

Result**✗ Failed****Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge down to cushion rubber and on legal limit. (5.2.3 (e))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Brake pad(s) wearing thin with closer inspection maybe to excess. (1.1.13 (a) (ii))**MOT #10**

2018-11-22 14:33

MOT test number

908315090755

Result**✓ Passed****Advice** Rear Child Seat fitted not allowing full inspection of adult belt 2 x seats fitted**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened offside rear slight bind and rear application uneven but not to excess. (1.1.14 (a) (ii))**MOT #9**

2018-11-22 10:48

MOT test number

951316610422

Result**✗ Failed****Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt 2 x seats fitted**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened offside rear slight bind and rear application uneven but not to excess. (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm ball joint has slight play almost to excess (5.3.4 (a) (i))

**MOT #8**

2017-11-25 10:35

MOT test number

892612075756

Result

✓ Passed

- Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Play in steering rack inner joint(s) both sides
- Advice** Nearside Front Tyre worn close to the legal limit worn on both inner and outer edges (4.1.E.1)

MOT #7

2016-11-29 10:24

MOT test number

500019283594

Result

✓ Passed

- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Offside Front tyre low on outer edges (smooth)
- Advice** Offside Front rack gaiter area sweat/oily
- Advice** Wiper blades poor split almost to excess
- Advice** Offside Rear perished and cracked

MOT #6

2016-11-29 10:24

MOT test number

576615834319

Result

✗ Failed

- Advice** Offside Front tyre low on outer edges (smooth)
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Advice** Offside Front rack gaiter area sweat/oily
- Advice** Wiper blades poor split almost to excess
- Advice** Offside Rear perished and cracked
- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**MOT #5** 2015-11-25 09:26**MOT test number** 677879364867**Result** ✓ Passed

- Advice** Nearside Rear nailed
- Advice** Oil leak/spillage apparent oil leaking on to offside front suspension arm and hub area.
- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Nearside Front tyre outer sidewall small bulge apparent.
- Advice** Offside wiper blade poor ends split but not to excess.

MOT #4 2015-11-24 10:07**MOT test number** 566450842255**Result** ✗ Failed

- Advice** Oil leak/spillage apparent oil leaking on to offside front suspension arm and hub area.
- Advice** Nearside Rear Brake pad(s) wearing thin slight bind apparent,evidence apparent disc has been hot. (3.5.1g)
- Advice** Nearside Front tyre outer sidewall small bulge apparent.
- Advice** Offside wiper blade poor ends split but not to excess.
- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Nearside Rear nailed

MOT #3 2014-11-26 11:27**MOT test number** 437250634325**Result** ✓ Passed

- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2013-11-25 12:38
MOT test number	905359523379
Result	✓ Passed

MOT #1	2012-11-23 10:30
MOT test number	148948222345
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	Front pads 60 - 70% Worn



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
30 November 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-30
Last registration	2023-11-28
Complete history	See info



Registration #1	2009-11-30	27 mi
Registration #2	2012-11-23	44.398 mi
Registration #3	2013-11-25	51.975 mi
Registration #4	2014-11-26	59.682 mi
Registration #5	2015-11-24	69.108 mi
Registration #6	2015-11-25	69.111 mi
Registration #7	2016-11-29	78.504 mi
Registration #8	2016-11-29	78.504 mi
Registration #9	2017-11-25	86.231 mi
Registration #10	2018-11-22	94.815 mi
Registration #11	2019-11-22	103.400 mi
Registration #12	2020-11-22	111.985 mi
Registration #13	2021-11-22	120.570 mi
Registration #14	2022-11-22	129.155 mi
Registration #15	2023-11-22	137.740 mi
Registration #16	2023-11-22	146.325 mi
Registration #17	2023-11-22	154.910 mi
Registration #18	2023-11-22	163.495 mi
Registration #19	2023-11-22	172.080 mi
Registration #20	2023-11-22	180.665 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D095480