



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA EXCLUSIV CDTI 8V
Colour	Blue
Year of manufacture	2008
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2021-08-13
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	21
Total items failed	12

MOT #16 2020-08-14 16:05

MOT test number 124205371773

Result ✓ Passed

Next expiry date 2021-08-13

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15 2020-08-07 12:41

MOT test number 784695215285

Result ✗ Failed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Driver's door cannot be opened from inside the vehicle (6.2.3 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2019-08-09 17:28

MOT test number

166266944471

Result

✓ Passed

Advice Items removed from driver's view prior to test**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2019-08-09 09:44

MOT test number

408802108197

Result

✗ Failed

Fail Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))**Fail** Offside Rear Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Items removed from driver's view prior to test**Fail** Nearside Rear Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Brake performance not tested (1.2.1 (g))**MOT #12**

2018-08-06 10:01

MOT test number

354223079353

Result

✓ Passed

Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

**MOT #11** 2018-08-04 12:14**MOT test number** 611897861267**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2018-07-28 10:07**MOT test number** 165427390702**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Front tyres worn on edges**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2017-08-03 13:15**MOT test number** 224716236746**Result** ✓ Passed**MOT #8** 2016-07-14 09:38**MOT test number** 373639689415**Result** ✓ Passed**MOT #7** 2015-08-10 10:33**MOT test number** 838202825268**Result** ✓ Passed**MOT #6** 2014-08-04 14:36**MOT test number** 578956214261**Result** ✓ Passed

**MOT #5** 2013-07-29 14:42**MOT test number** 147540913206**Result** ✓ Passed**MOT #4** 2013-07-29 10:40**MOT test number** 156730113245**Result** ✗ Failed**Fail** Offside Rear coil spring fractured (2.4.C.1a)**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**MOT #3** 2012-08-01 11:34**MOT test number** 459764212248**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2011-08-08 18:16**MOT test number** 357930521476**Result** ✓ Passed**Notice** Both rear tyres worn to excess on inner edges only**MOT #1** 2011-07-12 11:58**MOT test number** 888733891155**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FH08XFV
Plate since	2019-03-29
Current registration	 FH08XFV
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-08-01
Last registration	2020-08-14
Complete history	See info



Registration #1	2008-08-01	28 mi
Registration #2	2011-07-12	52.967 mi
Registration #3	2011-08-08	53.551 mi
Registration #4	2012-08-01	62.176 mi
Registration #5	2013-07-29	70.235 mi
Registration #6	2013-07-29	70.235 mi
Registration #7	2014-08-04	77.425 mi
Registration #8	2015-08-10	92.223 mi
Registration #9	2016-07-14	105.221 mi
Registration #10	2016-07-14	105.221 mi
Registration #11	2016-07-14	105.221 mi
Registration #12	2016-07-14	105.221 mi
Registration #13	2016-07-14	105.221 mi
Registration #14	2016-07-14	105.221 mi
Registration #15	2016-07-14	105.221 mi
Registration #16	2016-07-14	105.221 mi
Registration #17	2016-07-14	105.221 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1428 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	6036771