



LL10AZF

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX SE TSI
Colour	Silver
Year of manufacture	-
Top speed	135 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	240 Nm at 1.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

**MOT history****MOT #15**

2023-01-24 09:51

**MOT test number**

587416017599

**Result****✗ Failed****Fail** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Emissions not tested excessive smoke emitted (8.2.1.2 (d))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14**

2022-02-01 18:11

**MOT test number**

229691461084

**Result****✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged misshaping on outer edge (5.2.3 (d) (ii))**Minor** Offside Windscreen damaged but not adversely affecting driver's view scratched (3.2 (a) (i))**Advice** Spare tyre defective flat**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))



MOT #13

2022-02-01 14:22

MOT test number

621128812733

Result

✗ Failed

- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Rear Tyre slightly damaged misshaping on outer edge (5.2.3 (d) (ii))
- Minor

Offside Windscreen damaged but not adversely affecting driver's view scratched (3.2 (a) (i))
- Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor

Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail

Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice

Spare tyre defective flat

**MOT #12**

2022-01-26 11:08

**MOT test number**

241490427816

**Result****✗ Failed**

**Minor** Offside Windscreen damaged but not adversely affecting driver's view SCRATCHED ALONG WIPER (3.2 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 185/60H14 (5.2.3 (d) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**Advice** Spare tyre defective FLAT

**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 185/60H14 (5.2.3 (d) (ii))

**Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

**Advice** FUEL CAP SEAL PERISHED

**MOT #11**

2021-02-08 16:58

**MOT test number**

960761320767

**Result****✓ Passed****MOT #10**

2021-02-05 11:18

**MOT test number**

133993198493

**Result****✗ Failed**

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**MOT #9** 2020-01-03 16:57**MOT test number** 227605790839**Result** ✓ Passed**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #8** 2020-01-03 12:09**MOT test number** 562662944958**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii))**Fail** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2018-08-15 08:52**MOT test number** 812477655100**Result** ✓ Passed**MOT #6** 2017-07-14 14:17**MOT test number** 406997720754**Result** ✓ Passed

**MOT #5** 2017-07-14 09:40**MOT test number** 713535308971**Result** ✗ Failed

- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #4** 2016-07-25 08:55**MOT test number** 918170379777**Result** ✓ Passed**MOT #3** 2015-01-08 13:57**MOT test number** 368298105079**Result** ✓ Passed**MOT #2** 2015-01-06 14:07**MOT test number** 146326705015**Result** ✗ Failed

- Notice** Epc warning light on
- Fail** Centre Rear Stop lamp remains on when the brakes are released (1.2.1e)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Stop lamp not working (1.2.1b)



MOT #12013-07-01 13:07

MOT test number378612083127

Result

Passed

- Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>LL10AZF</b>
Plate since	2019-06-29
Current registration	<b>LL10AZF</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-27
Last registration	2023-01-24
Complete history	<a href="#">See info</a>



Registration #1	2010-05-27	7 mi
Registration #2	2013-07-01	17.451 mi
Registration #3	2015-01-06	29.278 mi
Registration #4	2015-01-08	29.279 mi
Registration #5	2016-07-25	41.308 mi
Registration #6	2017-07-14	47.149 mi
Registration #7	2017-07-14	47.150 mi
Registration #8	2018-08-15	55.669 mi
Registration #9	2020-01-03	64.252 mi
Registration #10	2020-01-03	64.252 mi
Registration #11	2020-01-03	64.252 mi
Registration #12	2020-01-03	64.252 mi
Registration #13	2020-01-03	64.252 mi
Registration #14	2020-01-03	64.252 mi
Registration #15	2020-01-03	64.252 mi
Registration #16	2020-01-03	64.252 mi
Registration #17	2020-01-03	64.252 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2009 mm
Height	1444 mm
Length	4423 mm
Wheel base	2578 mm
Kerb weight	1487 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CAV 199717