





General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Black
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 2	
Date	2021-06-18
Pictures	35
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #8		2023-05-16 11:06
MOT test	number	287562234315
Result		✓ Passed
Next expi	ry date	2024-05-15
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7	2023-05-05 16:37
MOT test number	718542813584
Result	🗙 Failed
Fail Offside Rear Headlamp levelling device inoperative (4.1.5 (a))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2022-04-29 15:31
MOT test number	290282665217
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #5	2022-04-29 12:22
MOT test number	632481698463
Result	🗙 Failed
AdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))FailNearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #4	2021-04-02 14:21
MOT test number	966748007311
Result	✓ Passed

МОТ #3	2021-01-11 16:38
MOT test number	362057179619
Result	✓ Passed

MOT #2		2019-07-12 14:42
MOT test	number	175247846059
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords sid	ewall (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge centre (5.2.3 (e))	
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords tread	d (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge centre (5.2.3 (e))	

MOT #1	2018-05-10 09:27
MOT test number	133696998239
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 15 May 2024
Tax status	Valid until 1 September
Days left	124
MOT expiry date	15 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lashe
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	 *
Category	 amer
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

ACCOUNTS OF A DESCRIPTION OF A DESCRIPTI	
NUMBER OF CONTRACT OF CONTRACT.	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-30
Last registration	2023-05-16
Complete history	See info



Registration #1	2015-05-30	13 mi
Registration #2	2018-05-10	27.703 mi
Registration #3	2019-07-12	38.713 mi
Registration #4	2021-01-11	49.592 mi
Registration #5	2021-04-02	49.795 mi
Registration #6		11.117 esi
Registration #7		
Registration #8		10.000 est
Registration #8 Registration #9		11.117 est 11.117 est 11.117 est

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1712 kg
Max. allowed weight	2140 kg
Additional information	
Fuel tank capacity	58
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	
-----------------	--

Engine number

D4HAFZ093695