



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S AC ECOFLEX
Colour	Red
Year of manufacture	2013
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 1

Date	2022-08-06
Pictures	26
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	6

MOT #10	2023-08-09 14:10
MOT test number	510256386257
Result	✓ Passed
Next expiry date	2024-08-08
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Offside Rear Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))

**MOT #9**

2023-08-09 10:46

MOT test number

579831586835

Result**✗ Failed****Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Offside Rear Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #8**

2022-08-08 16:40

MOT test number

214844320444

Result**✓ Passed****MOT #7**

2022-07-06 14:16

MOT test number

685172695452

Result**✗ Failed****Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #6** 2021-09-09 13:05**MOT test number** 114696339141**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2020-10-13 14:53**MOT test number** 843133485292**Result** ✓ Passed**MOT #4** 2019-10-03 10:49**MOT test number** 758364605734**Result** ✓ Passed**MOT #3** 2018-10-02 08:28**MOT test number** 500280213065**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2017-09-27 14:18**MOT test number** 223227352248**Result** ✓ Passed**MOT #1** 2016-10-10 12:51**MOT test number** 478473132108**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
8 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	PK63YAX
Plate since	2019-06-29
Current registration	PK63YAX
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-18
Last registration	2023-08-09
Complete history	See info



Registration #1	2013-10-18	20 mi
Registration #2	2016-10-10	26.633 mi
Registration #3	2017-09-27	42.703 mi
Registration #4	2018-10-02	58.726 mi
Registration #5	2019-10-03	71.937 mi
Registration #6	2020-10-13	78.421 mi
Registration #7	2021-05-20	85.277 mi
Registration #8	2021-05-20	91.277 mi
Registration #9	2021-05-20	97.277 mi
Registration #10	2021-05-20	103.277 mi
Registration #11	2021-05-20	109.277 mi
Registration #12	2021-05-20	115.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	985 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	K10B - 1610584LUX