





report date: 2024-03-29

General information

Make	MINI
Model	ONE AUTO ONE
Colour	Red
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	140 Nm at 4.000 rpm
Engine capacity	1.397 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	42.8 mpg
CO2 emission	157 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1


Date 2022-02-26

Pictures 56

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-27
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	10
Total items failed	6

MOT #20	2024-02-28 15:14
MOT test number	576905534840
Result	✓ Passed
Next expiry date	2025-02-27
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #19		2024-02-28 15:14
MOT test number		239230901715
Result		X Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Fuel cap/sealing device ineffective (6.1.3 (b) (i))	

MOT #18		2024-02-28 13:52
MOT test	number	563130909105
Result		× Failed
MAJOR	Fuel cap/sealing device ineffective (6.1.3 (b) (i))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #17 2024-02-28 13:39

MOT test number 900002178225

Result X Failed

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Nearside Registration plate lamp does not illuminate simultaneously with the

position lamps (4.7.2 (a))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

MAJOR Fuel cap/sealing device ineffective (6.1.3 (b) (i))

MOT #16 2023-02-17 15:47

MOT test number 654649286714

Result \(\sqrt{Passed} \)

MOT #15 2023-02-16 12:30

MOT test number 417488177405

Result X Failed

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2

(a))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14 2022-02-26 16:07

MOT test number 995478931122

Result ✓ Passed

MOT #13 2021-09-29 11:43

MOT test number 254250620321

Result

Passed

CarCheck.co.uk page 4/13



report date:	2024-03-29
--------------	------------

MOT #12	2020-09-16 11:29
MOT test number	964850015451
Result	✓ Passed
MOT #11	2019-09-17 13:47
MOT test number	135975171333
Result	✓ Passed
MOT #10	2018-09-14 11:36
MOT test number	870441705006
Result	✓ Passed
MOT #9	2017-09-18 13:32
MOT test number	318479622541
Result	✓ Passed
MOT #8	2016-09-13 15:15
MOT test number	622140941591
Result	✓ Passed
MOT #7	2016-09-13 13:34
MOT test number	836741571907
Result	× Failed
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	

MOT #6	2015-09-17 13:27
MOT test number	342427511656
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #5	2014-09-19 16:48
MOT test number	198612864272
Result	✓ Passed
MOT #4	2013-09-17 14:34
MOT test number	196950163200
Result	✓ Passed
MOT #3	2012-09-05 11:59
MOT test number	569669242232
Result	✓ Passed
MOT #2	2011-08-30 15:52
MOT test number	527782041239
Result	✓ Passed
MOT #1	2010-09-21 11:02
MOT test number	512184560244
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



LB07PLN report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-18
Last registration	2024-02-28
Complete history	See info



2007-06-18	26 mi
2010-09-21	4.312 mi
2011-08-30	4.722 mi
2012-09-05	4.987 mi
2013-09-17	5.362 mi
2014-09-19	7.017 mi
2015-09-17	8.852 mi
2016-09-13	10.879 mi
2016-09-13	10.879 mi
2017-09-18	13.104 mi
2018-09-14	15.465 mi
	11.777 es
	9.777 es
	11.777 es
	91.777 esi
	11.777 es
	91.777 esi
	11.777 es
	91.777 esi
	11.777 es
	11.777 es
	0.00 44
	2010-09-21 2011-08-30 2012-09-05 2013-09-17 2014-09-19 2015-09-17 2016-09-13 2016-09-18 2018-09-14

More info >

CarCheck.co.uk page 12/13



LB07PLN report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number CarCheck.co.uk	A090H975 page 13/13