



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Grey
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	171 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-02-12
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-06
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	28
Total items failed	15

MOT #20 2024-03-07 09:54

MOT test number 264670687899

Result ✓ Passed

Next expiry date 2025-03-06

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19 2023-02-04 11:09

MOT test number 553451239414

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush (5.3.4 (a) (i))

MOT #18 2023-02-03 17:52

MOT test number 570815619833

Result ✗ Failed

Fail Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush (5.3.4 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn rear arm bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2022-02-10 16:33**MOT test number** 849229464233**Result** ✓ Passed**Advice** Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))**MOT #16** 2021-01-28 15:23**MOT test number** 673482770389**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2021-01-28 11:55**MOT test number** 738884386953**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #14** 2020-01-17 11:42**MOT test number** 750807463877**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-01-17 11:42**MOT test number** 322133770400**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2019-01-16 12:20**MOT test number** 182168789947**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-01-12 14:08**MOT test number** 801602846630**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #10**

2018-01-12 10:29

MOT test number

493710597647

Result**✗ Failed**

- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Steering rack insecure (2.2.B.1a)

MOT #9

2017-01-17 13:05

MOT test number

741384066834

Result**✓ Passed****MOT #8**

2016-01-20 09:40

MOT test number

208917113057

Result**✓ Passed**

- Advice** Under trays and engine covers fitted

MOT #7

2016-01-15 09:28

MOT test number

486502116827

Result**✗ Failed**

- Fail** Nearside Headlamp aim too high and too far to the right. will not adjust (1.8)
- Advice** Under trays and engine covers fitted
- Fail** Offside Headlamp aim too far to the right will not adjust (1.8)

**MOT #6** 2015-01-12 10:19**MOT test number** 898802315053**Result** ✓ Passed**MOT #5** 2014-01-10 09:32**MOT test number** 906100414069**Result** ✓ Passed**Notice** Offside front tyre is worn to 1.6mm.**Notice** The Legal minimum requirement is 1.6mm. Tyre size 205/55x16H.**Notice** Nearside rear tyre is worn to 2.0mm.**MOT #4** 2013-01-10 09:04**MOT test number** 109010713004**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-01-19 08:28**MOT test number** 467509212022**Result** ✓ Passed**MOT #2** 2012-01-19 08:28**MOT test number** 148359112431**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)



MOT #1	2011-01-14 15:15
MOT test number	608084711098
Result	✓ Passed
Advice	Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-01
Last registration	2024-03-07
Complete history	See info



Registration #1	2008-03-01	19 mi
Registration #2	2011-01-14	26.238 mi
Registration #3	2012-01-19	31.246 mi
Registration #4	2013-01-10	38.045 mi
Registration #5	2014-01-10	43.851 mi
Registration #6	2015-01-12	50.144 mi
Registration #7	2016-01-15	56.265 mi
Registration #8	2016-01-20	56.311 mi
Registration #9	2017-01-17	62.106 mi
Registration #10	2018-01-12	69.391 mi
Registration #11	2018-01-12	69.391 mi
Registration #12	2019-01-20	75.277 mi
Registration #13	2019-01-20	75.277 mi
Registration #14	2019-01-20	75.277 mi
Registration #15	2019-01-20	75.277 mi
Registration #16	2019-01-20	75.277 mi
Registration #17	2019-01-20	75.277 mi
Registration #18	2019-01-20	75.277 mi
Registration #19	2019-01-20	75.277 mi
Registration #20	2019-01-20	75.277 mi
Registration #21	2019-01-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	124162