



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 EXCLUSIVE HDI
Colour	Silver
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	11.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	314 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg
CO2 emission	186 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-02-17
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-19
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	20
Total items failed	2

MOT #19	2023-08-18 12:57
MOT test number	168521606382
Result	✓ Passed
Next expiry date	2024-08-19
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18	2023-08-12 09:56
MOT test number	929049795978
Result	✗ Failed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
MAJOR	Offside Front Parking brake inoperative on one side (1.4.1 (a))
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
MAJOR	Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #17** 2022-08-20 10:32**MOT test number** 190360760088**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Slightly corroded (1.1.11 (c))**MOT #16** 2022-08-19 10:34**MOT test number** 479153751400**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Slightly corroded (1.1.11 (c))**MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))**MOT #15** 2021-08-20 13:00**MOT test number** 130810926787**Result** ✓ Passed**MOT #14** 2020-10-06 09:16**MOT test number** 940894298209**Result** ✓ Passed**MOT #13** 2019-03-27 11:46**MOT test number** 513663480479**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-03-19 14:40**MOT test number** 598898402982**Result** ✓ Passed

**MOT #11** 2017-03-14 16:35**MOT test number** 687147350863**Result** ✓ Passed**MOT #10** 2016-03-17 09:15**MOT test number** 954233617091**Result** ✓ Passed**MOT #9** 2015-03-25 12:17**MOT test number** 477304485095**Result** ✓ Passed**MOT #8** 2014-03-18 14:02**MOT test number** 108157974031**Result** ✓ Passed**MOT #7** 2013-03-25 11:16**MOT test number** 817044783024**Result** ✓ Passed**Advice** Rear Fluid suspension unit supply pipe corroded but not seriously weakened (2.4.D.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2012-03-31 11:55**MOT test number** 817481092079**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #5** 2012-03-23 14:01**MOT test number** 268853682057**Result** ✗ Failed**Fail** Nearside Front Fluid suspension pipe leaking (2.4.D.2)**Fail** Nearside Front Fluid suspension unit leaking (2.4.D.2)**MOT #4** 2011-03-18 10:45**MOT test number** 625207471020**Result** ✓ Passed**MOT #3** 2010-03-26 10:40**MOT test number** 583275480075**Result** ✓ Passed**Notice** Child seat fitted to n/s/r seat belt not tested**MOT #2** 2009-03-21 09:49**MOT test number** 383590289036**Result** ✓ Passed**MOT #1** 2008-03-03 12:15**MOT test number** 734803168091**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
19 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-05-29
Current registration	
Plate since	2019-05-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-04
Last registration	2023-08-18
Complete history	See info



Registration #1	2005-03-04	12 mi
Registration #2	2008-03-03	29.309 mi
Registration #3	2009-03-21	36.220 mi
Registration #4	2010-03-26	42.044 mi
Registration #5	2011-03-18	48.239 mi
Registration #6	2012-03-23	56.060 mi
Registration #7	2012-03-31	56.149 mi
Registration #8	2013-03-25	71.324 mi
Registration #9	2014-03-18	77.091 mi
Registration #10	2015-03-25	81.233 mi
Registration #11	2016-03-17	88.001 mi
Registration #12	2016-03-20	91.277 mi
Registration #13	2016-03-20	91.277 mi
Registration #14	2016-03-20	91.277 mi
Registration #15	2016-03-20	91.277 mi
Registration #16	2016-03-20	91.277 mi
Registration #17	2016-03-20	91.277 mi
Registration #18	2016-03-20	91.277 mi
Registration #19	2016-03-20	91.277 mi
Registration #20	2016-03-20	91.277 mi
Registration #21	2016-03-20	91.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1475 mm
Length	4745 mm
Wheel base	2750 mm
Max. allowed weight	2078 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ544003490