

Ford



### General information

Make	FORD
Model	C-MAX ZETEC
Colour	Brown
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	11.5 seconds
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	92 kW / 125 HP / 104 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F







### Internet history

Entry 1	
Date	2021-11-04
Pictures	3

Listing price

View report







source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	13
Total items failed	1

MOT #10	2023-11-23 15:50
MOT test number	410967574744
Result	✓ Passed
Next expiry date	2024-12-01

MOT #9		2023-11-23 15:10
MOT test numbe	er	464296993389
Result		🗙 Failed
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

2022-12-02 11:19
998279718527
✓ Passed

MOT #7	2021-07-09 14:23
MOT test number	368471189069
Result	✓ Passed





MOT #6	2020-06-19 12:22
MOT test number	221337026949
Result	✓ Passed
MOT #5	2019-04-16 10:00
MOT test number	425227568399
Result	✓ Passed

MOT #4	2018-04-17 11:15
MOT test number	620275160405
Result	✓ Passed
Advice Front brake pads wearing thin	
Advice Front and rear brake discs have slight wear	
Advice Rear brake pads wearing thin	

МОТ #3	2018-04-17 11:15	
MOT test number	495708491696	
Result	× Failed	
Advice Rear brake pads	wearing thin	
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Front brake pads wearing thin		
Advice Front and rear b	rake discs have slight wear	

MOT #2	2017-02-25 09:27
MOT test number	207314280328
Result	✓ Passed
Advice Child Seat fitted not allowing full inspection of adult belt	
<b>Advice</b> Nearside Rear Shock absorber has a light misting of oil (2.7.3)	





MOT #1		2016-02-18 15:08
MOT test nun	nber	777472982904
Result		✓ Passed
<b>Advice</b> Ne	earside Front Tyre worn close to the legal limit tyre 3mm (4.1.E.1)	
<b>Advice</b> Of	fside Front Tyre worn close to the legal limit tyre 3mm (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 1 December 2024
Tax status	Valid until 1 December
Days left	217
MOT expiry date	1 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-04
Last registration	2023-11-23
Complete history	<u>See info</u>



Registration #1	2013-05-04	19 mi
Registration #2	2016-02-18	20.688 mi
Registration #3	2017-02-25	27.542 mi
Registration #4	2018-04-17	34.896 mi
Registration #5	2018-04-17	34.896 mi
Registration #6	2019-04-16	44.064 mi
Registration #7		11.117 esi
Registration #7 Registration #8		10.000 est
		10.200 est 10.200 est 10.200 est
Registration #8		10.200 est 10.200 est 10.200 est 10.200 est
Registration #8 Registration #9		10.202 46 0.202 46 0.202 46 0.202 46 0.202 46





## Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
\$0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	2067 mm
Height	1626 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1274 kg
Max. allowed weight	1860 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12