



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B








Internet history

Entry 1

Date	2021-05-26
Pictures	30
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-04-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	15
Total items failed	9

MOT #15	2023-03-29 12:03
MOT test number	863455663141
Result	✓ Passed
Next expiry date	2024-04-05
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-04-01 08:36
MOT test number	113333979281
Result	✓ Passed

MOT #13	2021-03-09 14:07
MOT test number	224842363440
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2021-03-09 08:05**MOT test number** 934987242390**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2020-03-06 09:37**MOT test number** 362715579719**Result** ✓ Passed**MOT #10** 2019-04-02 10:45**MOT test number** 705841932946**Result** ✓ Passed**MOT #9** 2018-04-04 11:02**MOT test number** 824042347680**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2018-04-04 09:17**MOT test number** 137789093384**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #7** 2017-04-06 10:47**MOT test number** 580040809754**Result** ✓ Passed**MOT #6** 2016-05-16 11:44**MOT test number** 195008572546**Result** ✓ Passed**MOT #5** 2016-05-11 11:45**MOT test number** 995824513116**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2015-06-02 09:27**MOT test number** 866643655106**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-05-16 10:41**MOT test number** 109546234158**Result** ✓ Passed



MOT #2	2014-05-15 11:23
MOT test number	615915534177
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #1	2013-05-16 10:58
MOT test number	325086733184
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✗
MOT
Expired:
5 April 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	5 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-24
Last registration	2023-03-29
Complete history	See info



Registration #1	2010-04-24	7 mi
Registration #2	2013-05-16	48.389 mi
Registration #3	2014-05-15	59.283 mi
Registration #4	2014-05-16	59.283 mi
Registration #5	2015-06-02	72.299 mi
Registration #6	2016-05-11	88.672 mi
Registration #7	2016-05-16	88.673 mi
Registration #8	2017-04-06	92.905 mi
Registration #9	2018-04-04	94.612 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602