




report date: 2024-03-28

## General information

Make	VAUXHALL
Model	MOVANO R3500 L3H3 P/V CDTI
Colour	White
Year of manufacture	2015
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	32.5 mpg
Consumption combined	30.1 mpg
CO2 emission	246 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-21
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-28
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	12
Total items failed	11

MOT #9	2023-07-07 14:21
MOT test number	684002391021
Result	✓ Passed
Next expiry date	2024-07-28
Advice	N/s/r trim panel and body marker missing
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #8	2022-07-29 14:51
MOT test number	757079246984
Result	✓ Passed
Advice	N/s/r trim panel and body marker missing

MOT #7	2021-07-02 08:20
MOT test number	265785882302
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2020-07-13 13:08
MOT test number	909277115524
Result	✓ Passed

**MOT #5** 2020-07-13 13:08**MOT test number** 827034201535**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Rear fog lamp not working (4.5.1 (a) (ii))**MOT #4** 2019-06-06 09:53**MOT test number** 701199873573**Result** ✓ Passed**Advice** Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))**MOT #3** 2019-06-06 09:53**MOT test number** 464105941633**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Pass with rectification** Nearside Outline marker lamp not working X2 (4.2.1 (a))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Offside Outline marker lamp not working X2 (4.2.1 (a))**Advice** Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #2** 2018-06-29 13:35**MOT test number** 563316695075**Result** ✓ Passed



MOT #12018-06-26 15:44

MOT test number653422729334

Result

Failed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Body component likely to become detached Trim pannel (6.2.1 (a) (ii))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Fail

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice

Nearside Rear Lens damaged



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
28 July 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	28 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>DF15HYJ</b>
Plate since	2019-03-28
Current registration	 <b>DF15HYJ</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-30
Last registration	2023-07-07
Complete history	<a href="#">See info</a>



Registration #1	2015-06-30	21 mi
Registration #2	2018-06-26	49.815 mi
Registration #3	2018-06-29	49.817 mi
Registration #4	2019-06-06	52.817 mi
Registration #5	2019-06-06	52.817 mi
Registration #6	2020-07-13	58.983 mi
Registration #7	2023-07-07	58.983 mi
Registration #8	2023-07-07	58.983 mi
Registration #9	2023-07-07	58.983 mi
Registration #10	2023-07-07	58.983 mi
Registration #11	2023-07-07	58.983 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2470 mm
Height	2786 mm
Length	6198 mm
Kerb weight	2148 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	M9T -C021204 L2U