



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Black
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-10-02
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-15
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	16
Total items failed	8

MOT #16	2024-01-16 16:14
MOT test number	719458148184
Result	✓ Passed
Next expiry date	2025-01-15

MOT #15	2024-01-08 14:02
MOT test number	251935174016
Result	✗ Failed
Fail	Offside Side repeater not working (4.4.1 (a) (ii))
Fail	Offside Side repeater lens defective such that the emitted light is adversely affected lens missing (4.4.1 (b) (ii))

MOT #14	2023-01-16 15:39
MOT test number	616378498626
Result	✓ Passed
Advice	Front number plate cracked

MOT #13	2023-01-16 15:39
MOT test number	986922655194
Result	✗ Failed
Advice	Front number plate cracked
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #12** 2021-12-09 14:48**MOT test number** 999648897584**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyres perished DOM 2015/2017....
(5.2.3 (d) (ii))**Advice** Offside Rear trailing arm bush starting to delaminate...**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge.. (5.2.3 (e))**MOT #11** 2021-12-08 15:28**MOT test number** 599661649517**Result** ✗ Failed**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyres perished DOM 2015/2017....
(5.2.3 (d) (ii))**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt small end
insecure (2.1.3 (g) (i))**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge.. (5.2.3 (e))**Advice** Offside Rear trailing arm bush starting to delaminate...**MOT #10** 2021-01-04 16:43**MOT test number** 425123586185**Result** ✓ Passed**MOT #9** 2021-01-04 16:43**MOT test number** 231385996596**Result** ✗ Failed**Pass with rectification** Steering rack gaiter missing or no longer prevents the ingress of dirt both sides
(2.1.3 (g) (ii))

**MOT #8** 2019-05-22 09:49**MOT test number** 789202109817**Result** ✓ Passed**MOT #7** 2019-05-11 11:09**MOT test number** 403609961891**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2018-04-30 15:27**MOT test number** 458612960074**Result** ✓ Passed**MOT #5** 2017-03-25 12:04**MOT test number** 900561256378**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear tyre perishing**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front tyre has sidewall damage**Advice** Both rear tyres wearing on inner edges**MOT #4** 2016-02-26 12:33**MOT test number** 826880639549**Result** ✓ Passed



MOT #3	2016-02-26 12:33
MOT test number	395331058386
Result	✗ Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2	2015-02-25 09:19
MOT test number	706336155066
Result	✓ Passed

MOT #1	2014-03-07 10:47
MOT test number	729776964021
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
15 January 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-01
Last registration	2024-01-16
Complete history	See info



Registration #1	2011-03-01	27 mi
Registration #2	2014-03-07	56.988 mi
Registration #3	2015-02-25	76.189 mi
Registration #4	2016-02-26	94.623 mi
Registration #5	2016-02-26	94.623 mi
Registration #6	2017-03-25	111.459 mi
Registration #7	2018-04-30	118.280 mi
Registration #8	2019-05-11	122.781 mi
Registration #9	2019-05-22	122.800 mi
Registration #10	2019-05-22	122.800 mi
Registration #11	2019-05-22	122.800 mi
Registration #12	2019-05-22	122.800 mi
Registration #13	2019-05-22	122.800 mi
Registration #14	2019-05-22	122.800 mi
Registration #15	2019-05-22	122.800 mi
Registration #16	2019-05-22	122.800 mi
Registration #17	2019-05-22	122.800 mi
Registration #18	2019-05-22	122.800 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1895 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	933852