



RENAULT



report date: 2024-03-28

General information

| | |
|---------------------|--------------------|
| Make | RENAULT |
| Model | MEGANE EXTREME DCI |
| Colour | Grey |
| Year of manufacture | - |
| Top speed | 109 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 85 BHP |
| Max. torque | 200 Nm at 1.750 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 62.8 mpg |



LABEL UNKNOWN

**MOT history**

| | |
|-------------------------|--|
| MOT #19 | 2023-09-01 14:43 |
| MOT test number | 446795235928 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-31 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Minor | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |

| | |
|--------------------------------|--|
| MOT #18 | 2023-08-31 15:29 |
| MOT test number | 491808733283 |
| Result | ✗ Failed |
| Minor | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Pass with rectification | Offside Side repeater incorrect colour (4.4.3 (a)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) |

| | |
|------------------------|------------------|
| MOT #17 | 2022-08-03 12:59 |
| MOT test number | 377959429993 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #16 | 2021-08-26 10:59 |
| MOT test number | 766689908100 |
| Result | ✓ Passed |

| | |
|------------------------|-------------------|
| MOT #15 | 2020-08-25 16:17 |
| MOT test number | 439017816076 |
| Result | ✓ Passed |
| Advice | Under tray fitted |

**MOT #14**

2020-08-25 08:44

MOT test number

526832902375

Result**✗ Failed****Advice** Under tray fitted**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #13**

2019-08-21 16:27

MOT test number

663825528786

Result**✓ Passed****Advice** Under tray fitted**Advice** Nearside front daytime running light not working**Advice** Nearside rear tyre outer edges slightly perished**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12**

2019-08-21 08:48

MOT test number

764976843433

Result**✗ Failed****Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Under tray fitted**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Brake fluid contaminated (1.8 (a))**Advice** Nearside front daytime running light not working**Advice** Nearside rear tyre outer edges slightly perished

**MOT #11**

2018-08-28 14:54

MOT test number

730423206986

Result

✓ Passed

Minor

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10

2018-08-28 08:21

MOT test number

336157143182

Result

✗ Failed

Minor

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Brake fluid contaminated (1.8 (a))

Fail

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #9

2017-08-16 11:39

MOT test number

258179962580

Result

✓ Passed

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #8

2017-08-14 10:19

MOT test number

921493968483

Result

✗ Failed

Fail

Horn not working (1.6.2a)

Fail

Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail

Offside Front Headlamp not working on dipped beam (1.7.5a)

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

Fail

Nearside Front Shock absorber has a serious fluid leak (2.7.3)

Fail

Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #7** 2016-08-19 08:16**MOT test number** 879548032734**Result** ✓ Passed**MOT #6** 2015-08-14 15:28**MOT test number** 746996825288**Result** ✓ Passed**MOT #5** 2015-08-07 10:28**MOT test number** 856219815269**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nail in nearside rear tyre**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2014-08-29 14:58**MOT test number** 358951844238**Result** ✓ Passed**MOT #3** 2014-08-27 09:14**MOT test number** 627849734237**Result** ✗ Failed**Fail** Offside Front rear brake binding (3.7.B.1)**Fail** Nearside Rear rear brake binding (3.7.B.1)



MOT #2 2013-08-27 10:34

MOT test number 638439533277

Result ✓ Passed

Notice Items removed from driver's view prior to test

Notice Under-trays fitted obscuring some underside components

MOT #1 2013-08-27 10:34

MOT test number 398569033262

Result ✗ Failed

Pass with rectification Offside Headlamp aim too low (1.8)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Items removed from driver's view prior to test

Pass with rectification Offside Side repeater not working (1.4.A.2c)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Under-trays fitted obscuring some underside components



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-28 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|---------|------|
| Finance company | RENAULT | 2024 |
| Date of agreement | RENAULT | 2024 |
| Agreement type | RENAULT | 2024 |
| Agreement term | RENAULT | 2024 |
| Agreement number | RENAULT | 2024 |
| Contact info | RENAULT | 2024 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2010-09-28 |
| Last registration | 2023-09-01 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-09-28 | 12 mi |
| Registration #2 | 2013-08-27 | 20.106 mi |
| Registration #3 | 2014-08-27 | 26.067 mi |
| Registration #4 | 2014-08-29 | 26.111 mi |
| Registration #5 | 2015-08-07 | 30.944 mi |
| Registration #6 | 2015-08-14 | 31.004 mi |
| Registration #7 | 2016-08-19 | 37.707 mi |
| Registration #8 | 2017-08-14 | 43.992 mi |
| Registration #9 | 2017-08-16 | 43.992 mi |
| Registration #10 | 2018-08-28 | 52.760 mi |
| Registration #11 | 2019-08-28 | 59.557 mi |
| Registration #12 | 2020-08-28 | 66.354 mi |
| Registration #13 | 2021-08-28 | 73.151 mi |
| Registration #14 | 2022-08-28 | 79.948 mi |
| Registration #15 | 2023-08-28 | 86.745 mi |
| Registration #16 | 2023-08-28 | 93.542 mi |
| Registration #17 | 2023-08-28 | 100.339 mi |
| Registration #18 | 2023-08-28 | 107.136 mi |
| Registration #19 | 2023-08-28 | 113.933 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2037 mm |
| Height | 1471 mm |
| Length | 4295 mm |
| Wheel base | 2641 mm |
| Max. allowed weight | 1743 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

Engine number

D051706