





General information

Make	ΤΟΥΟΤΑ
Model	LAND CRUISER D-4D LC4
Colour	Grey
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	410 Nm at 2.800 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	35.3 mpg
Consumption combined	30.7 mpg
CO2 emission	243 g/km
CO2 label	L







Internet history

Entry 1

Date Pictures 2022-01-16

20

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	21
Total items failed	6

MOT #20	2024-01-12 09:42
MOT test number	299434906318
Result	✓ Passed
Next expiry date	2025-01-11

MOT #19		2024-01-03 10:07
MOT test	number	669006943748
Result		× Failed
MAJOR	Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))	
MAJOR	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	
MAJOR	Offside Front Brake pipe excessively corroded (1.1.11 (c))	
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
MAJOR	Nearside Front Brake pipe excessively corroded (1.1.11 (c))	
DANGER	OUS Nearside Front Wheel bearing play so excessive it is likely to break up (5	5.1.3 (a) (ii))
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Brake performance unable to be tested (1.2.1 (g))	





MOT #18	2023-01-10 15:12
MOT test number	231637191535
Result	✓ Passed
MOT #17	2023-01-10 10:27
MOT test number	710541566702
Result	🗙 Failed
MAJOR Offside Rear fog lamp not working (4.5.1 (a) (ii))	
MOT #16	2021-09-13 10:22
MOT test number	229604443507
Result	✓ Passed
MOT #15	2020-10-13 12:23
MOT test number	863460488816
Result	✓ Passed
MOT #14	2019-04-09 14:07
MOT test number	414791951461
Result	✓ Passed
MOT #13	2019-04-09 08:54
MOT test number	357089676339
Result	× Failed
MAJOR Nearside Front Inner Drive shaft joint constant velocity boot split or insecure,	no longer prevents
the ingress of dirt small end clip broken (6.1.7 (g) (ii))	
MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	

MOT #12	2018-04-06 14:06
MOT test number	666606486527
Result	✓ Passed



MOT #11	2018-04-06 09:00
MOT test number	186485332495
Result	🗙 Failed
Fail Nearside rear brake binding (3.7.B.1)	
MOT #10	2017-04-06 13:08
MOT test number	616334861046
Result	✓ Passed
МОТ #9	2017-04-06 08:30
MOT test number	568249560469
Result	🗙 Failed
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

FailNearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

FailNearside Rear Exhaust system not adequately supported (7.1.1)

MOT #8	2016-04-02 08:35
MOT test number	376700051078
Result	✓ Passed

MOT #7	2015-04-16 10:38
MOT test number	376896205187
Result	✓ Passed
Notice Passenger seat(s) missing at time of test	







MOT #6	2015-04-16 10:38
MOT test number	245936705456
Result	× Failed
Pass with rectification reach the ply or cords (4.1.0	Nearside Rear Tyre has a cut in excess of the requirements deep enough to 0.1a)
Notice Passenger seat(s) missing at time of test
Pass with rectification the ply or cords (4.1.D.1a)	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach
MOT #5	2014-04-02 14:46
MOT test number	129812994405
Result	✓ Passed
Notice Both rear tyres p	perishing (07)
MOT #4	2013-04-09 12:33
MOT test number	959639093094

Result

MOT #3	201	2-04-02 15:25
MOT test	number 6	37663792025
Result		🗸 Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	

✓ Passed





MOT #2		2011-04-19 09:21
MOT test	number	155909601183
Result		✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Notice	Both front tyres are bold on inner and outer edges.	
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)	

MOT #1	2010-04-16 11:42
MOT test number	983686200103
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 11 January 2025
Tax status	Valid until 1 February
Days left	278
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-04-24
Last registration	2024-01-12
Complete history	See info



Registration #1	2007-04-24	22 mi
Registration #2	2010-04-16	24.200 mi
Registration #3	2011-04-19	32.870 mi
Registration #4	2012-04-02	42.856 mi
Registration #5	2013-04-09	62.019 mi
Registration #6	2014-04-02	68.155 mi
Registration #7	2015-04-16	74.665 mi
Registration #8	2016-04-02	81.270 mi
Registration #9	2017-04-06	87.696 mi
Registration #10	2017-04-06	87.696 mi
Registration #11	2018-04-06	92.896 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.117 mi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
50566	
S0567	
S0569	

Safety ratings

Number of seats

Number of axles

NCAP rating	****
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight	
Width	1875 mm
Height	1905 mm
Length	4405 mm
Wheel base	2790 mm
Kerb weight	2180 kg
Max. allowed weight	2850 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5

8

2