





report date: 2024-03-28

General information

Make	BMW
Model	320 320D XDRIVE M SPORT
Colour	Blue
Year of manufacture	2016
Top speed	142 mph
0 - 60 mph	7.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history


Entry 1

Date 2021-06-14

Pictures 60

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2025-04-11
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #7	2024-04-12 15:19
MOT test number	675958542201
Result	✓ Passed
Next expiry date	2025-04-11

MOT #6		2023-04-12 16:17
MOT test	number	227122153865
Result		✓ Passed
Advice	Under body tray and covers fitted obscuring some testable items	
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Stop lamp light intensity low	

MOT #5		2022-04-11 12:25
MOT test	number	200628523147
Result		✓ Passed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Child Seat fitted not allowing full inspection of adult belt	

MOT #4	2021-03-06 11:49
MOT test number	110734629032
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT test number

Result

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre slightly damaged outer edge (5.2.3 (d) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged outer edge (5.2.3 (d) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2019-11-08 11:53

MOT test number 208690425619

Result × Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11





Tax & MOT check





Tax status	Expired at 26 April 2024
Days left	3 days too late
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	hictory
Owner	HISLOFY

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)		e?

	More info >	,
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	>

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-26
Last registration	2024-04-12
Complete history	See info



Registration #1	2016-09-26	23 mi
Registration #2	2019-11-08	33.098 mi
Registration #3	2020-03-26	36.262 mi
Registration #4	2020-03-26	36.262 mi
Registration #5	2021-03-06	42.053 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1434 mm
Length	4633 mm
Wheel base	2810 mm
Kerb weight	1535 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	57 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 55019544