



report date: 2024-03-28

General information

Make	MAZDA
Model	3 TS2
Colour	Silver
Year of manufacture	2006
Top speed	124 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	187 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	44.8 mpg
Consumption combined	34.5 mpg
CO2 emission	196 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-05-24
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-14
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	48
Total items failed	8

MOT #20	2023-06-08 10:31
MOT test number	520234601474
Result	✓ Passed
Next expiry date	2024-06-14
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #19	2022-06-09 10:03
MOT test number	826079748111
Result	✓ Passed

MOT #18	2021-06-02 15:21
MOT test number	217814283167
Result	✓ Passed

**MOT #17** 2021-06-01 11:03**MOT test number** 985317305498**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm damaged and seriously weakened (5.3.3 (b) (i))**MOT #16** 2020-06-15 11:01**MOT test number** 721740837692**Result** ✓ Passed**MOT #15** 2019-05-22 08:15**MOT test number** 693945992037**Result** ✓ Passed**MOT #14** 2018-07-09 14:26**MOT test number** 217645937925**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Nearside Front Nail in tyre**Minor** Nearside Windscreen wiper blade defective split (3.4 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Rear Nail in tyre**Minor** Offside Registration plate lamp insecure (4.7.1 (c) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**MOT #13**

2017-06-20 15:25

MOT test number

216870088239

Result

✓ Passed

- Advice** Corrosion exhaust system
- Advice** Power steering pipe(s) or hose(s) has slight seepage From resevoir (2.3.3b)
- Advice** Nearside Front Seat belt twisted
- Advice** Rear Both tyres worn and cracking

MOT #12

2017-06-20 08:37

MOT test number

295601830082

Result

✗ Failed

- Advice** Rear Both tyres worn and cracking
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Power steering pipe(s) or hose(s) has slight seepage From resevoir (2.3.3b)
- Advice** Corrosion exhaust system
- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Front Seat belt twisted
- Advice** Offside Rear Nail in tyre

**MOT #11**

2016-06-20 08:35

MOT test number

455176163237

Result

✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened nearside+offside (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #10

2015-06-26 10:45

MOT test number

278907075119

Result

✓ Passed

Advice Nearside Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Nearside wiper blade split

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9

2015-06-25 12:05

MOT test number

438256275110

Result

✗ Failed

Fail Electronic stability system warning lamp indicates a fault (3.4.1c)

Advice Nearside Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Headlamp aim too low (1.8)

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Nearside wiper blade split

Fail Offside Headlamp aim too low (1.8)



MOT #8	2014-06-18 12:14
MOT test number	387169364119
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
Advice	Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
Notice	Engine management lamp on

MOT #7	2014-06-18 11:25
MOT test number	718089264164
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
Advice	Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #6	2014-05-24 15:14
MOT test number	635604844172
Result	✗ Failed
Advice	Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
Fail	Nearside Headlamp cleaning device inoperative (1.7.2)

**MOT #5** 2013-07-31 11:54**MOT test number** 517992313282**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2012-07-06 10:02**MOT test number** 219088882495**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2011-06-22 14:32**MOT test number** 585223971141**Result** ✓ Passed**MOT #2** 2010-07-06 16:57**MOT test number** 920227480192**Result** ✓ Passed**MOT #1** 2009-06-18 15:17**MOT test number** 601329469130**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-31
Last registration	2023-06-08
Complete history	See info



Registration #1	2006-03-31	17 mi
Registration #2	2009-06-18	20.367 mi
Registration #3	2010-07-06	23.547 mi
Registration #4	2011-06-22	31.123 mi
Registration #5	2012-07-06	42.641 mi
Registration #6	2013-07-31	51.386 mi
Registration #7	2014-05-24	56.045 mi
Registration #8	2014-06-18	56.107 mi
Registration #9	2014-06-18	119.945 mi
Registration #10	2015-06-25	61.223 mi
Registration #11	2015-06-26	61.226 mi
Registration #12	2015-06-26	61.226 mi
Registration #13	2015-06-26	61.226 mi
Registration #14	2015-06-26	61.226 mi
Registration #15	2015-06-26	61.226 mi
Registration #16	2015-06-26	61.226 mi
Registration #17	2015-06-26	61.226 mi
Registration #18	2015-06-26	61.226 mi
Registration #19	2015-06-26	61.226 mi
Registration #20	2015-06-26	61.226 mi
Registration #21	2015-06-26	61.226 mi
Registration #22	2015-06-26	61.226 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4420 mm
Wheel base	2640 mm
Kerb weight	1369 kg
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 624370