





report date: 2024-03-28

#### General information

Make	FIAT
Model	PUNTO EVO MULTIJET SPORTING
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	120 BHP
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-07-30

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-04-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	15
Total items failed	5

MOT #16	2024-04-11 12:38
MOT test number	310990680402
Result	<b>✓</b> Passed
Next expiry date	2025-04-21

MOT #15	2023-04-05 14:30
MOT test number	625047795832
Result	✓ Passed

MOT #14	2022-04-15 15:22
MOT test number	409989903414
Result	✓ Passed

MOT #13	2021-04-22 15:54
MOT test number	348449938680
Result	✓ Passed

MOT #12	2021-04-16 13:27
MOT test number	919227466503
Result	<b>≍</b> Failed
Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	
Fail Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

Result

Fail Front Brake disc significantly and obviously worn both sides (1.1.14 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

MOT test number

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear silencer corroded

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2017-07-20 08:00

MOT test number 278150013720

Result ✓ Passed

**MOT #6** 2016-07-21 09:42

**MOT test number** 363860090528

**Advice** Offside Rear Outer Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)

MOT #5 2015-07-30 14:29

**MOT test number** 387321515414

Result \rightarrow Passed

**Advice** Brake pad(s) wearing thin (3.5.1g)

**Notice** Under-trays fitted obscuring some underside components

**Notice** Engine covers fitted obscuring some components in the engine bay

MOT #4 2014-11-20 15:42

MOT test number 499664824460

Result 

Passed

MOT #3 2014-11-20 10:19

MOT test number 836194724354

**Result** X Failed

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2 2014-02-26 11:16

**MOT test number** 485397554093

**Result** ✓ Passed

**MOT #1** 2014-02-25 16:42

**MOT test number** 197246654017

**Result** X Failed

**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	21 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13




report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report h		e?
THE STATE OF THE S		
***************************************		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK CONTRACTOR	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

**Contact info** 

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-02-28
Last registration	2024-04-11
Complete history	See info



Registration #1	2011-02-28	14 mi
Registration #2	2014-02-25	46.015 mi
Registration #3	2014-02-26	46.015 mi
Registration #4	2014-11-20	50.172 mi
Registration #5	2014-11-20	50.172 mi
Registration #6	2015-07-30	53.012 mi
Registration #7	2016-07-21	57.910 mi
Registration #8	2017-07-20	71.446 mi
Registration #9	2018-07-27	80.868 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1190 kg
Max. allowed weight	1750 kg

## Additional information

Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5 page 1	3/13