



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA S TINO
Colour	Black
Year of manufacture	2004
Top speed	108 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	44.8 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 2


Date	2022-02-06
Pictures	2
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-05
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	29
Total items failed	7

MOT #20	2023-05-10 11:00
MOT test number	891316376433
Result	✓ Passed
Next expiry date	2024-05-09
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #19**

2023-05-09 12:50

MOT test number

706902126003

Result**✗ Failed****Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Brakes imbalanced across an axle 43% (1.2.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 28% (1.2.1 (b) (i))**MOT #18**

2022-03-09 08:58

MOT test number

461653689569

Result**✓ Passed****Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2022-03-09 08:58**MOT test number** 422954666011**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #16** 2021-03-18 17:40**MOT test number** 934513658132**Result** ✓ Passed**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2020-03-07 12:06**MOT test number** 892666527171**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-03-25 12:01**MOT test number** 110805399581**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #13** 2018-03-27 11:05**MOT test number** 224634433016**Result** ✓ Passed**MOT #12** 2018-03-24 10:53**MOT test number** 943744038651**Result** ✗ Failed

- Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Front wheel bearing has excessive play (2.5.A.3c)
- Advice** Items removed from driver's view prior to test
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** High level brake light not working.
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #11 2017-03-17 09:29**MOT test number** 421812446763**Result** ✓ Passed**MOT #10** 2016-03-18 09:33**MOT test number** 902878486361**Result** ✓ Passed**MOT #9** 2015-03-13 09:38**MOT test number** 558402775058**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Power steering component(s) has slight seepage from a component (2.3.3b)



MOT #8	2014-03-21 09:54
MOT test number	269960784083
Result	✓ Passed
MOT #7	2013-03-22 09:53
MOT test number	879511083028
Result	✓ Passed
MOT #6	2012-03-09 09:20
MOT test number	497959362039
Result	✓ Passed
MOT #5	2011-03-18 09:21
MOT test number	127307371412
Result	✓ Passed
MOT #4	2010-03-19 09:57
MOT test number	224908170087
Result	✓ Passed
MOT #3	2009-03-13 10:01
MOT test number	771282179040
Result	✓ Passed
MOT #2	2008-03-14 09:57
MOT test number	920964578066
Result	✓ Passed
MOT #1	2007-03-23 12:00
MOT test number	402012687024
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
9 May 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-03-30
Last registration	2023-05-10
Complete history	See info



Registration #1	2004-03-30	27 mi
Registration #2	2007-03-23	18.699 mi
Registration #3	2008-03-14	23.814 mi
Registration #4	2009-03-13	29.111 mi
Registration #5	2010-03-19	34.493 mi
Registration #6	2011-03-18	38.890 mi
Registration #7	2012-03-09	43.419 mi
Registration #8	2013-03-22	48.288 mi
Registration #9	2014-03-21	53.054 mi
Registration #10	2015-03-13	58.264 mi
Registration #11	2016-03-18	62.548 mi
Registration #12	2017-03-17	65.655 mi
Registration #13	2018-03-20	65.655 mi
Registration #14	2019-03-20	65.655 mi
Registration #15	2020-03-20	65.655 mi
Registration #16	2021-03-20	65.655 mi
Registration #17	2022-03-20	65.655 mi
Registration #18	2023-03-20	65.655 mi
Registration #19	2024-03-20	65.655 mi
Registration #20	2025-03-20	65.655 mi
Registration #21	2026-03-20	65.655 mi
Registration #22	2027-03-20	65.655 mi
Registration #23	2028-03-20	65.655 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1758 mm
Height	1608 mm
Length	4264 mm
Wheel base	2535 mm
Kerb weight	1420 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	326624