




report date: 2024-03-29

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Blue
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-30
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	4

MOT #9	2023-08-31 14:46
MOT test number	298911111360
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #8	2023-08-31 08:58
MOT test number	401970273568
Result	✗ Failed
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #7	2022-10-14 09:23
MOT test number	241079861666
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))

**MOT #6** 2021-10-13 08:03**MOT test number** 623394454402**Result** ✓ Passed**MOT #5** 2021-01-12 15:36**MOT test number** 402164044177**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2020-01-10 16:38**MOT test number** 547004349198**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2019-01-10 15:49**MOT test number** 985620852104**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #2** 2018-01-22 16:10**MOT test number** 740208624339**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front tyre has damage to outer sidewall**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #1	2016-06-13 13:47
MOT test number	610047674102
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Centre Standard fitment seat belt missing due to child seat



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
30 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	30 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-19
Last registration	2023-08-31
Complete history	<a href="#">See info</a>



Registration #1	2013-06-19	28 mi
Registration #2	2016-06-13	7.861 mi
Registration #3	2018-01-22	15.223 mi
Registration #4	2019-01-10	19.429 mi
Registration #5	2020-01-10	22.666 mi
Registration #6	2021-01-12	23.718 mi
Registration #7	2023-08-31	25.277 mi
Registration #8	2023-08-31	25.277 mi
Registration #9	2023-08-31	25.277 mi
Registration #10	2023-08-31	25.277 mi
Registration #11	2023-08-31	25.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

