



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CRTD GSI
Colour	Blue
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	191 Nm at 2.500 rpm
Cylinders	3
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg



LABEL UNKNOWN

**MOT history**

MOT #14	2021-10-21 08:04
MOT test number	366737721107
Result	✓ Passed
Next expiry date	2022-10-20

MOT #13	2020-10-14 09:47
MOT test number	149817525444
Result	✓ Passed
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material ALL STEEL PIPES (1.1.11 (c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2019-06-05 10:43
MOT test number	133119553089
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11	2018-05-31 09:00
MOT test number	312986840069
Result	✓ Passed
Advice	Offside Front Lower bottom ball joint cover



MOT #10	2018-05-31 09:00
MOT test number	542329493719
Result	✗ Failed
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
Advice	Offside Front Lower bottom ball joint cover

MOT #9	2017-05-22 13:59
MOT test number	595701230855
Result	✓ Passed
Advice	Items removed from driver's view prior to test
Advice	Oil leak engine
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8	2017-05-22 09:50
MOT test number	657289946255
Result	✗ Failed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)
Fail	Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
Advice	Nearside rear brake fluctuating, but not excessively (3.7.B.3)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Items removed from driver's view prior to test
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside rear brake excessively fluctuating (3.7.B.3)
Fail	Nearside Rear Brakes imbalanced across an axle lower effort than offside, giving brake imbalance (3.7.B.5b)
Advice	Oil leak engine
Fail	Offside Front Tyre tread depth below requirements of 1.6mm showing cord (4.1.E.1)



MOT #7	2016-04-25 09:32
MOT test number	953997143088
Result	✓ Passed
MOT #6	2015-04-28 14:16
MOT test number	528008615104
Result	✓ Passed
MOT #5	2014-05-08 16:20
MOT test number	828088024125
Result	✓ Passed
MOT #4	2013-04-06 13:36
MOT test number	616336893045
Result	✓ Passed
MOT #3	2013-04-06 10:03
MOT test number	436546393078
Result	✗ Failed
<div><div>Notice</div> N/s/r tyre is approaching the tread wear indicators 175/65/14/h</div> <div><div>Fail</div> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div> <div><div>Notice</div> Handbrake lever requires adjustment</div>	
MOT #2	2012-04-11 16:21
MOT test number	316052202100
Result	✓ Passed
MOT #1	2011-05-04 11:16
MOT test number	779244621147
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-06-14
Last registration	2021-10-21
Complete history	See info



Registration #1	2008-06-14	26 mi
Registration #2	2011-05-04	45.716 mi
Registration #3	2012-04-11	62.093 mi
Registration #4	2013-04-06	79.100 mi
Registration #5	2013-04-06	79.100 mi
Registration #6	2014-05-08	87.854 mi
Registration #7	2015-04-28	94.897 mi
Registration #8	2016-04-25	103.219 mi
Registration #9	2016-04-25	103.219 mi
Registration #10	2016-04-25	103.219 mi
Registration #11	2016-04-25	103.219 mi
Registration #12	2016-04-25	103.219 mi
Registration #13	2016-04-25	103.219 mi
Registration #14	2016-04-25	103.219 mi
Registration #15	2016-04-25	103.219 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1500 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1204 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FA8U514149