



report date: 2024-03-29

## General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2010
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-17
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-14
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	24
Total items failed	12

MOT #15 2023-07-05 13:44

MOT test number 402958812409

Result ✓ Passed

Next expiry date 2024-07-14

**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Play in steering rack inner joint(s)

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i))

MOT #14 2022-07-14 14:22

MOT test number 389243033407

Result ✓ Passed

**Advice** Rear under seal corroded

**MOT #13**

2022-07-14 14:22

**MOT test number**

393668828090

**Result****✗ Failed****Pass with rectification**

Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Pass with rectification**

Nearside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))

**Pass with rectification**

Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

**Pass with rectification**

Offside Front Road wheel fixing missing (5.2.1 (a) (i))

**Advice**

Rear under seal corroded

**MOT #12**

2021-07-15 06:34

**MOT test number**

468339722651

**Result****✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2021-07-14 13:42

**MOT test number**

547725510433

**Result****✗ Failed****Fail**

Nearside Rear Direction indicator incorrect colour FLASH WHITE (4.4.3 (a))

**Fail**

Offside Front Position lamp not working (4.2.1 (a) (ii))

**Fail**

Offside Rear Position lamp has a product on the lens or light source which shows white light to the rear SHOWS ORANGE LIGHT TO REAR (4.2.3 (b) (ii))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Offside Rear Direction indicator incorrect colour FLASH WHITE (4.4.3 (a))

**Fail**

Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail**

Nearside Rear Position lamp has a product on the lens or light source which shows white light to the rear SHOWS ORANGE LIGHT (4.2.3 (b) (ii))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2020-09-28 07:20**MOT test number** 442182047189**Result** ✓ Passed**MOT #9** 2019-09-24 07:07**MOT test number** 627710024577**Result** ✓ Passed

- Advice** Front brake pads worn low wear and corrosion to front brake discs
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Corrosion to front and rear coil springs
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-09-26 07:45**MOT test number** 945997575662**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2017-09-28 08:24**MOT test number** 345303820558**Result** ✓ Passed

- Advice** Offside rear tyre edge wearing low
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2016-09-29 10:42**MOT test number** 129116667106**Result** ✓ Passed

**MOT #5** 2016-09-29 08:46**MOT test number** 804332204279**Result** ✗ Failed**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**MOT #4** 2015-10-05 09:34**MOT test number** 683366998860**Result** ✓ Passed**Advice** N/s/f and o/s/f tyres wearing on inner edges**MOT #3** 2014-10-07 13:26**MOT test number** 756690884207**Result** ✓ Passed**MOT #2** 2014-10-07 10:19**MOT test number** 566230584209**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-09-25 10:13**MOT test number** 218158663215**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
14 July 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	14 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-29
Last registration	2023-07-05
Complete history	<a href="#">See info</a>



Registration #1	2010-09-29	19 mi
Registration #2	2013-09-25	34.591 mi
Registration #3	2014-10-07	47.755 mi
Registration #4	2014-10-07	47.755 mi
Registration #5	2015-10-05	59.471 mi
Registration #6	2016-09-29	73.203 mi
Registration #7	2016-09-29	73.203 mi
Registration #8	2017-09-28	88.387 mi
Registration #9	2018-09-26	104.137 mi
Registration #10	2019-09-26	121.277 mi
Registration #11	2019-09-26	121.277 mi
Registration #12	2019-09-26	121.277 mi
Registration #13	2019-09-26	121.277 mi
Registration #14	2019-09-26	121.277 mi
Registration #15	2019-09-26	121.277 mi
Registration #16	2019-09-26	121.277 mi
Registration #17	2019-09-26	121.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1347 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	AL29261