



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Black
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-07-31
Pictures	19
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-30
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-27
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	18
Total items failed	13

MOT #20	2023-07-27 14:47
MOT test number	837642169213
Result	✓ Passed
Next expiry date	2024-07-27
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2023-07-25 09:02
MOT test number	562775335410
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18** 2022-07-27 10:02**MOT test number** 186863419778**Result** ✓ Passed**Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))**MOT #17** 2021-07-28 12:05**MOT test number** 395009667977**Result** ✓ Passed**MOT #16** 2020-11-26 11:35**MOT test number** 281954827538**Result** ✓ Passed**Advice** Osf + osr rear seat belts slighty freyed**MOT #15** 2020-11-25 10:15**MOT test number** 576126904222**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Offside Front Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Nearside Rear Seat belt webbing significantly weakened (7.1.2 (b) (ii))**Fail** Nearside Front Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Osf + osr rear seat belts slighty freyed**MOT #14** 2019-12-04 15:22**MOT test number** 418311769305**Result** ✓ Passed

**MOT #13** 2019-12-04 13:35**MOT test number** 980405144269**Result** ✗ Failed

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #12 2018-12-06 14:01**MOT test number** 304672618395**Result** ✓ Passed**MOT #11** 2018-12-05 12:51**MOT test number** 220341925264**Result** ✗ Failed

Fail Offside Rear Upper Drag link end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10 2017-12-08 11:21**MOT test number** 454199207076**Result** ✓ Passed**MOT #9** 2016-12-12 13:05**MOT test number** 395132477881**Result** ✓ Passed

Advice Engine under tray fitted

**MOT #8** 2016-12-12 13:05**MOT test number** 564968736512**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Engine under tray fitted**MOT #7** 2015-12-07 13:44**MOT test number** 470532391341**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Vehicle engine covers and under trays fitted**MOT #6** 2014-11-25 14:24**MOT test number** 797989924345**Result** ✓ Passed**MOT #5** 2013-11-29 13:00**MOT test number** 628413533366**Result** ✓ Passed**Notice** Nail in nearside front tyre**MOT #4** 2013-11-29 10:28**MOT test number** 817623933303**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nail in nearside front tyre**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #3	2012-12-15 09:26
MOT test number	875780552311
Result	✓ Passed

MOT #2	2012-01-17 15:49
MOT test number	717117712071
Result	✓ Passed

MOT #1	2011-01-05 12:19
MOT test number	659955501092
Result	✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	RJ57FWL
Plate since	2019-06-29
Current registration	RJ57FWL
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-01-26
Last registration	2023-07-27
Complete history	See info



Registration #1	2008-01-26	16 mi
Registration #2	2011-01-05	17.723 mi
Registration #3	2012-01-17	24.839 mi
Registration #4	2012-12-15	31.254 mi
Registration #5	2013-11-29	34.966 mi
Registration #6	2013-11-29	34.967 mi
Registration #7	2014-11-25	40.520 mi
Registration #8	2015-12-07	44.468 mi
Registration #9	2016-12-12	49.162 mi
Registration #10	2016-12-12	49.162 mi
Registration #11	2017-12-08	52.915 mi
Registration #12	2018-12-05	56.425 mi
Registration #13	2019-01-01	56.425 mi
Registration #14	2019-01-01	56.425 mi
Registration #15	2019-01-01	56.425 mi
Registration #16	2019-01-01	56.425 mi
Registration #17	2019-01-01	56.425 mi
Registration #18	2019-01-01	56.425 mi
Registration #19	2019-01-01	56.425 mi
Registration #20	2019-01-01	56.425 mi
Registration #21	2019-01-01	56.425 mi
Registration #22	2019-01-01	56.425 mi
Registration #23	2019-01-01	56.425 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE A27658