





report date: 2024-03-29

General information

Make	BMW	
Model	640 640D M SPORT GRAN COUPE	
Colour	Grey	
Year of manufacture	2016	
Top speed	155 mph	
0 - 60 mph	5.4 seconds	
Gearbox	8 speed automatic	

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-12-24

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-12-23

Pictures 41

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



BW16VXD report date: 2024-03-29

MOT history

MOT expiry date	2025-01-02
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	1

MOT #8	2023-12-08 12:29
MOT test number	511277046032
Result	✓ Passed
Next expiry date	2025-01-02
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #7		2023-01-03 15:13
MOT test	number	772843319466
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6		2022-12-31 11:03
MOT test	number	498187835348
Result		× Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))		
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



BW16VXD report date: 2024-03-29

MOT #5 2021-12-21 10:19

MOT test number 721704317208

Result
✓ Passed

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2021-09-15 08:42

MOT test number 245079492798

Result
✓ Passed

MOT #3 2021-09-15 08:42

MOT test number 778789596947

Result X Failed

Pass with rectification Central Rear Seat belt buckle missing (7.1.2 (d))

MOT #2 2020-07-25 15:07

MOT test number 252037730876

Result

Passed

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2019-08-14 08:09

MOT test number 167591668104

Result

Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	2 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

e mier metery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report is	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	IIK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-07-22
Last registration	2023-12-08
Complete history	See info



Registration #1	2016-07-22	21 mi
Registration #2	2019-08-14	51.726 mi
Registration #3	2020-07-25	54.152 mi
Registration #4	2021-09-15	73.013 mi
Registration #5	2021-09-15	73.013 mi
Registration #6	2021-12-21	78.151 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		10.777 es

More info >

CarCheck.co.uk page 10/11



BW16VXD report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

\neg	imer		(ᅩ
		חשו	ns 1	V 1/1/	reirei	

Width	1894 mm
Height	1392 mm
Length	5007 mm
Wheel base	2968 mm
Kerb weight	1810 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	59519335

CarCheck.co.uk page 11/11