





report date: 2024-03-28

General information

| Make | MINI |
|---------------------|--------------------|
| Model | COUNTRYMAN ONE ONE |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 107 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 98 BHP |
|-------------------------|---------------------|
| Max. torque | 153 Nm at 3.000 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



ML11VUP

report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-04

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-06-07 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 1 |
| Total items failed | 2 |

| MOT #11 | 2023-06-05 15:02 |
|------------------|------------------|
| MOT test number | 562830204950 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-07 |

| MOT #10 | 2022-06-07 10:47 |
|--|------------------|
| MOT test number | 196183037693 |
| Result | ✓ Passed |
| Minor Offside Windscreen wiper blade defective (3.4 (b) (i)) | |

| MOT #9 | 2021-06-08 15:49 |
|-----------------|------------------|
| MOT test number | 139944146090 |
| Result | ✓ Passed |
| | |

| MOT #8 | 2020-11-11 16:18 |
|-----------------|------------------|
| MOT test number | 442308796832 |
| Result | ✓ Passed |

| MOT #7 | 2020-11-10 16:17 |
|--|------------------|
| MOT test number | 984655844588 |
| Result | X Failed |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |

CarCheck.co.uk page 3/11



Result

ML11VUP report date: 2024-03-28

✓ Passed

| MOT #6 | 2019-05-22 14:47 |
|--|------------------|
| MOT test number | 612738153060 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2019-05-22 09:04 |
| MOT test number | 279469056839 |
| Result | × Failed |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |

| Result | × Falled |
|--|------------------|
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |
| | |
| MOT #4 | 2017-07-05 16:10 |
| MOT test number | 703100063114 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2016-07-05 13:11 |
| MOT test number | 807975363493 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2015-06-24 12:48 |
| MOT test number | 988835975130 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2014-06-20 09:54 |
| MOT test number | 845841974110 |

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 34 |
| MOT expiry date | 7 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| William . | 40 |
|---|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| e union mestery | |
|--|-------------|
| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u> | |
| *************************************** | |
| | |
| *************************************** | |
| | |
| | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | |
| Current registration | NK NK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2011-07-05 |
| Last registration | 2023-06-05 |
| Complete history | See info |



| Registration #1 | 2011-07-05 | 9 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-06-20 | 15.319 mi |
| Registration #3 | 2015-06-24 | 19.337 mi |
| Registration #4 | 2016-07-05 | 22.105 mi |
| Registration #5 | 2017-07-05 | 25.486 mi |
| Registration #6 | 2019-05-22 | 32.308 mi |
| Registration #7 | 2019-05-22 | 32.308 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 0.777 66 |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1789 mm |
|---------------------|---------|
| Height | 1561 mm |
| Length | 4097 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1265 kg |
| Max. allowed weight | 1775 kg |

Additional information

| Fuel tank capacity | 47 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Number of axles 2

Engine number A793I985